HABITAS AURORA METRICON HANDOVER GUIDE

A project by





CONTENTS

Welcome to Habitas

Aurora - Connected Community

Aurora's Social Heart

Established Neighbourhood

General information

Nature Strips and fencing Modifications to your Property Home maintenance 6-Star energy sustainable living

Council, waste & services

Council

Waste collection

Electricity and gas

Telecommunications and internet

Water and recycled water

Public transport

Community facilities

Warranty & contacts

General

Your home

Defect liability process

How to inspect defects

Viewing and inspecting distances

90-day maintenance checklist

Maintaining your home

General maintenance Preparing tenants Appliances Electrical

4	Door and window hardware	22
5	Carpet	22
5	Floorboards and laminate flooring	23
7	Aluminium windows and sliding doors	23
9	Ventilation	24
	Stone benchtops	24
11	Tapware	25
11	Paint	25
11	Cupboard joinery	25
11	Stainless steel kitchen sink, laundry tub,	26
11	trims, etc.	26 26
12	Sanitary ware Caulking and sealants	20
12	Tiled surfaces and balcony	27
12	External paint	27
13	Ground conditions	27
13	Roofing material	28
13	Metricon handover checklist	29
13		
13 14	Metricon 3 month maintenance form	31
		31
14		31
14 15		31
14 15 15		31
14 15 15 15		31
14 15 15 15 17		31
14 15 15 15 17		31
14 15 15 15 17 19		31
14 15 15 15 17 19 20		31
14 15 15 17 19 20 21		31
14 15 15 17 19 20 21 21		31

YOUR PRIVATE ENCLAVE

AURORA'S SOCIAL HEART

WELCOME TO HABITAS

Dear Owners,

Congratulations on your settlement and welcome to Aurora Community.

This guide containing key information has been prepared to assist you with transitioning into your new home.

The soft copy of the same is contained on your Habitas USB.

Additional information is available on the Habitas Aurora Connect Website.

Development Victoria







AURORA -Connected Community

RETAIL & DINING

1	Αι	ırora Village
	Α	Aurora Village Medical Centre
	В	Erol's Fruit Shop
	С	Aurora Butchers
	D	Hamara Bazaar
	Е	Oregano's Bakehouse & Cafe
	F	Diletto
	G	Degani Aurora Epping
2	Pa	acific Epping
	I	Reading Cinemas
3	Co	ostco Epping
4	Вι	unnings Epping
5	Ep	pping North Shopping Centre
	J	Jetts 24 Hour Fitness
	κ	Epping North Medical Centre
	L	Lyndarum Family Dentist
6	W	estfield Plenty Valley
7	Fu	iture Southern Town Centre
8	М	elbourne Wholesale Market
9	Cı	reeds Farm Convenience Store
10	Ep	pping RSL & Bowls Club
ED	UC	ATION
11	Ec	lgars Creek Secondary

- Lagaro or cox occorriadi y
- 12 Edgars Creek Primary School
- 13 St Mary of the Cross MacKillop Primary
- 14 Harvest Home Primary
- 15 Epping Views Primary
- 16 Epping North YMCA Early Learning Centre
- 17 Wallaby Childcare
- 18 Story House Early Learning Centre
- 19 One Early Learning Centre
- 20 Epping Views Kindergarten
- 21 RMIT University Bundoora
- 22 La Trobe University Bundoora

PARKS & NATURE

23	Linear Park (Future Transport Corridor)
24	Habitas Conservation Reserve
25	Aurora Town Centre Park
26	Aurora Adventure Park
27	Aurora Park
28	Gammage Park
29	Lehmann's Farm Park
30	Treetops Park
31	Boardwalk Park
32	Harvest Home Recreation Reserve
33	Epping Recreation Reserve
34	Edgars Creek Reserve
35	Aurora Tennis Courts

COMMUNITY & HEALTH

- 36 Galada Community Centre
- 37 Northern Hospital Epping

TRANSPORT

38	Epping Train Station
39	Wollert West 357 – Bus Stop
40	Epping Station 358 – Bus Stop
41	Hike and Bike Trail (Future Transport Corridor)





Adventure Playgrounds

Aurora is home to spectacular adventure playgrounds and inclusive play spaces featuring kinetic play equipment. Discover a range of creatively designed playgrounds for curious children to explore, like the impressive Aurora Town Centre Park.

Cycling tracks and walking trails

A 1.4km walking cycling path, an abundance of wideopen spaces and modern sporting facilities form the core of a thriving community.

Explore more than 20km of walking trails and allage cycle paths, connecting the heart of Aurora with various parks, open spaces and the natural landscape.

AURORA'S Social Heart

Live where vibrant activity intersects with natural beauty. Your opportunity to embrace the dynamic Aurora lifestyle is now within reach at Habitas. Your own home in a flourishing, established community.





Sports fields and sports courts

No matter your passion – cricket, soccer, lawn bowls, cycling, tennis, basketball, netball or running - you'll find a local club or group to join. AFL football ovals and tennis courts already await you at Aurora. Proposed future recreation facilities include soccer pitches, a sports pavilion, bocce courts and a lawn bowls area.

ESTABLISHED NEIGHBOURHOOD

Aurora Village's thriving hub is located conveniently on your doorstep, complete with employment, education, shopping, dining and lifestyle choices. From a quick weeknight shop to dinner with friends, it's all right here for you.









A one-hectare protected woodland reserve Habitas Conservation Reserve is home to various species of federally protected flora and fauna. The important preservation of this reserve, and others at Aurora, will ensure the biodiversity values of native vegetation and wildlife are protected into the future.

The Aurora masterplan protects 14 conservation reserves across the development. These ecologically significant sites, along with the Edgars Creek Corridor contribute to the sense of place and local character.

GENERAL INFORMATION

NATURE STRIPS AND FENCING

Development Victoria will be completing the streetscape works to the nature strips fronting your home in the second half of 2025. This will include grass and street tree planting.

It is the owner's responsibility to maintain their front nature strip and the owner must comply with guidelines set by the City of Whittlesea.

Please visit the <u>City of Whittlesea website</u> for more information.

Whilst boundary fencing is being supplied with the delivery of your new home, any modifications to this fencing must comply with local council requirements.

MODIFICATIONS TO YOUR PROPERTY

Any modifications to your property must comply with Memorandum of Common Provisions (MCP) registered against the title of the property. A copy is available in your original contract of sale documentation with Development Victoria or accessible via the Habitas Connect Portal.

If you are unsure, please reach out for clarification.

HOME MAINTENANCE

It is the owner's responsibility to suitably maintain their new home including all fixtures and fittings. General details are supplied within the Handover Guide and detailed product information has been provided on your Habitas Aurora USB to provide guidance on how each product should be maintained.

6-STAR ENERGY SUSTAINABLE LIVING

All Habitas townhouses are efficiently designed with increased insulation, with some sustainable inclusions such as skylights and double glazing (where applicable). By using less energy to maintain a comfortable year round temperature, home owners can minimise their carbon footprint and energy bills.

COUNCIL, **WASTE & SERVICES**

COUNCIL

Aurora is located in the City of Whittlesea's City of Whittlesea is responsible for waste collection in the Aurora estate. Southwest Ward. City of Whittlesea has a range of information for new residents When you move in OR prior to moving into available on its website at whittlesea.vic. your home - please contact the council to gov.au. arrange for your waste bins to be delivered to you. Council will also be able to provide info on the rubbish collection days.

The council's Civic Centre office is at 25 Ferres Boulevard, South Morang.

Postal address: Locked Bag 1, Bundoora MDC VIC 3083

Hours: 8.30am to 5pm Monday to Friday

p: (03) 9217 2170 (24 hours)

e: info@whittlesea.vic.gov.au



WASTE COLLECTION

Aurora property owners can book a free hard rubbish collection from their nature strip twice a year. Further information is available on the council's website.



ELECTRICITY AND GAS

You will need to set up a retail account with a provider to supply electricity to your home. It is recommended that you visit compare.energy.vic.gov.au to choose and compare energy deals.

Should you lose services to your property please contact your local authorities.

Electricity authority: SP Ausnet Services Ausnet p: <u>1300 001 001</u>

Gas Authority: Australian Gas Networks p: <u>1300 360 795</u>

TELECOMMUNICATIONS AND INTERNET

NBN services are available to your property. For further information on connecting to this service please visit <u>nbnco.com.au</u> or phone 1800 687 626.

You will need to set up a retail account with your preferred internet provider to arrange for set-up and connection to the NBN network.

Should you lose internet to your property please contact your retail provider to confirm there is no outage or planned maintenance in your area.

WATER AND RECYCLED WATER

Yarra Valley Water is your local water authority.

For general enquiries: p: 1300 304 688

For water or sewerage emergencies: p: <u>132 762</u>

w: yvw.com.au

Your new home is water efficient by design. The amount of water you use can be much less than the average household because of smart features like recycled water and efficient showerheads, taps and toilets.

Recycled water is plumbed directly to your property via the purple third pipe and connected to external irrigation and internal toilet flushing.

Please refer to the documentation for maintenance and care located on your USB. Please refer to Yarra Valley Water website for more info on recycled water.

PUBLIC TRANSPORT

A regular bus service operates throughout Aurora.

For more information phone the PTV Information Centre on 1800 800 007 or visit ptv.vic.gov.au.

COMMUNITY FACILITIES

The Aurora estate is home to a number of parks with playgrounds, exercise stations, seating and barbecue facilities.

The parks within the estate are maintained by the City of Whittlesea council.

To find your nearest park, visit the City of Whittlesea website.

Works to deliver the Habitas Linear Park will commence in the second half of 2025 and should be available for resident enjoyment in 2025.

Links to underlined documents can be accessed via the electronic copy on your USB.



WARRANTY **& CONTACTS**

GENERAL

Your new home comes complete with Builder and statutory warranties. Should something not seem to work as it was intended, please follow this guide to determine next steps.

When you take possession of your home, please read the manuals provided on your USB and ensure you complete any registrations required.

Please note that the Home Owner is responsible for maintenance of the home and footings. For further information please refer to the Handover Guide, your Habitas USB and the <u>Victorian Building Authority</u> Information sheet: Minimising foundation movement and damage to your house for further information.

YOUR HOME

The table provides an easy guide to assessing items within your home.

	GENERAL ITEMS	MODERATE ITEMS	URGENT ITEMS
What is the item?	Most items will fall under this category	 One toilet is blocked but the others are functioning One shower is leaking during operation but the others are fine Basin and Tapware leaks Minor power fault – for example one power point or downlight not operating 	 ✓ No power to the property after checking local outages and the safety switch in the switchboard ✓ Roof leak ✓ All toilets are blocked ✓ All heating and cooling not functioning ✓ Hot water service not functioning
What should you do?	Keep a note and present at your 90-day inspection (details on <u>page 17</u>)	Email: <u>TownLivingWarranty@metricon.com.au</u> and cc <u>habitas@development.vic.gov.au</u> include your address and "MEDIUM PRIORITY REQUEST" in the subject line. Outline the issue and if possible, include pho- tos.	Email: <u>TownLivingWarranty@metricon.com.au</u> and cc <u>habitas@development.vic.gov.au</u> include your address and "HIGH PRIORITY REQUEST" in the subject line. Outline the issue and if possible, include photos
Time to action	See 90-day inspection details for timing	24 hours	If you do not receive a response please call the Metricon direct (<u>1300Metricon</u> during business hours).
Please Note:		t instance for all items. Should you engage the tra d an emergency or as a result of the Builder's work	

DEFECT LIABILITY PROCESS

While every care was taking during the construction of your home, there can sometimes be minor issues that are not apparent until the home is occupied and operated.

The Builder will book an inspection to review these approximately 90-days after handover.

The below will assist you in preparing for this visit.

Should you have any further questions please reach out to your builder on <u>1300Metricon</u> or email <u>TownLivingWarranty@metricon.com.au</u>

	1-90 DAYS AFTER SETTLEMENT	76 DAYS AFTER SETTLEMENT	90 DAYS AFTER SETTLEMENT	STEP 1 90-DAY PROCESS	STEP 2 90-DAY PROCESS	STEP 3 90-DAY PROCESS	STEP 4 90-DAY PROCESS	AFTER 90-DAYS
Time	Days 1-90 after settlement	76 days after settlement	90 days after settlement					
What is it?	Getting to know your house period	Email reminder that you have enjoyed your home for almost 90-days and to send your list of concerns in shortly	Email your list of concerns to emails as noted in your Handover Guide	A Builder representative will contact you to book an appointment	A Builder representative will review your list and issue a list of items and trades that will be in contact to organise access	Trades will call directly to organise access to rectify items	Once trades have attended, Builder will notify you to confirm all your items have been attended to	Warranties that remain part of the home.
What you need to have ready	Compile a list of items you would like the Builder to look at. To determine if an issue requires urgent attention, refer to page 19 of this Guide.	Ensure you have your email updated.	List of concerns compiled on provided sheet	Be available for a call or email	Be available to show the Builder your items	Arrange access for trades to undertake works	Your list updated in case any items were missed.	Refer to the following documentation: ✓ <u>VBA Guide to</u> <u>Standards and</u> <u>Tolerances</u> ✓ Product Manuals Supplied on the Habitas USB

HOW TO INSPECT DEFECTS

VIEWING AND INSPECTING DISTANCES

Generally, variations in the surface colour, texture and finish of walls, ceilings, floors and roofs, and variations in glass and similar transparent materials are to be viewed where possible from a normal viewing position. A normal viewing position is looking at a distance of 1.5m or greater (600 mm for appliances and fixtures) with the surface or material being illuminated by 'non-critical light'. Non-critical light means the light that strikes the surface is diffused and is not glancing or parallel to that surface.



90-DAY MAINTENANCE CHECKLIST

Address (incl. lot no#): Primary contact name: Number: Email:

Property Manager details (if applicable):

ITEM	LOCATION	DESCRIPTION		BUILDER USE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
MINOR	ITEMS THAT GENERALLY	/ MAY REQUIRE REVIEW AT 90 DAY	MAINTENANCE INSPECT	
	se door handles	Door/window operation	Cabinetry adjustmen	
- LOC	se uoor rianules		Cabinetry aujustillen	13

If you need additional space, please print a copy from your digital version of the Handover Guide. At 90 days post settlement please identify any outstanding defects and send to TownLivingWarranty@metricon.com.au and Habitas@development.vic.gov.au

In accordance with VBA Guide to Standards and Tolerances https://www.vba.vic.gov.au/building/building-resource-hub/publications



MAINTAINING **YOUR HOME**

GENERAL MAINTENANCE

It is very important that you maintain your home to ensure the longevity of its finishes and fixtures. Please review the maintenance information below as well as any owner's manuals in regard to care and maintenance, and always use experienced and licenced tradespeople to carry out repairs and maintenance work.

As the home owner, you are responsible for the cleaning and maintenance of your home and all areas within your lot, including (where applicable) your balcony, terraces, roof and gutters.



PREPARING TENANTS

It is the responsibility of the home owner to provide this document to any property occupants (i.e. tenants) to ensure they understand the necessary safety precautions for completing routine maintenance and are aware of the safety tips and procedures highlighted in this document that are relevant to living in the home and Habitas development.

APPLIANCES

Refer to the manufacturer's instructions / operation manuals for the following appliances:

- Cooktop
- Oven
- Dishwasher
- Rangehood
- Air Conditioner
- Hot Water Service

ELECTRICAL

Should your safety switch trip for any reason, follow these steps:

- 1. Isolate / turn off all power points and lights and unplug all appliances.
- 2. Reset the safety switch.
- 3. If the safety switch cannot be reset, contact a licensed electrician as a fault exists with either the wiring or the switch itself.

- 4. Turn on the power points one at a time or until the safety switch trips. When it trips, you have found the faulty outlet.
- 5. Plug your appliances back into power points one at a time or until the safety switch trips. When it trips, you have determined the cause of the fault. Take the faulty appliance to a qualified service centre for repairs.

For safety reasons, ensure an adequate air space is left around the switchboard. Do not store items in front of or in contact with the switchboard.

Please note that a licensed electrician must be engaged to locate and fix any fault with the power supply or the switchboard.

DOOR AND WINDOW HARDWARE

To maintain a high level of function, door hardware must be free from dust and grit. Generally, all components can be cleaned with a soft damp cloth. Grease or oil should not be applied to any hardware.

Maintain door locks and handles every 6-12 months, as necessary:

- Tighten fixing screws;
- Re-align strike plates;
- Lubricate internal mechanism with an Light coloured carpets should be aerosol lubricant: and professionally cleaned every 6-12 months, Lubricate "sticky" locks with dry to maintain a satisfactory appearance of powder graphite sprinkled on the key. the carpet.



CARPET

defect.

Carpet in your home (where applicable) has been selected to provide a soft, maintainable, yet durable floor finish. Permanent pile reversal shading "watermarking" may appear at random. This variation in lightening or darkening of the carpet is caused by the reflection of light from pile tufts which lay in different directions. This does not constitute a

Regular maintenance will increase the life span of all types of carpet. The five basic steps of an adequate maintenance program are:

- Protection from damage and prevention of spills;
- Regular vacuuming; Intermediate surface brightening;
- Periodic wet cleaning; and •
- Removal of stains and spills. •

Please note that "scotch guarding" carpet is not recommended by the manufacturers.



FLOORBOARDS AND LAMINATE FLOORING

Floorboards and Laminate Flooring can be very susceptible to the below:

- Damage from water / moisture
- Damage / scratching from shoes and furniture.

It is strongly recommended that floor protection is installed when moving furniture into the property and that shoes are removed when on the flooring system. Damage from shoes and moving furniture is not a defect.

Water and moisture will significantly damage the flooring system. Any water on the flooring system should be removed immediately. Floors should be cleaned with a dry mop or damp cloth only.

ALUMINIUM WINDOWS AND SLIDING DOORS

Aluminium windows and doors have a powder coated finish, which needs to be cleaned and maintained regularly to ensure the decorative and protective properties of the coating are retained.

Cleaning is recommended every three to six months to remove air born deposits such as salt, dust and dirt.

To clean:

- Remove dust with a wet sponge (rather than risk micro scratching by dry dusting);
- Remove any marks by the use of a warm, mild detergent or mineral turpentine;
- Wash and remove powder deposits from the powder coating surface using a soft bristle brush; and
- Always rinse afterwards with fresh water so that the contact time with the cleaning solution is kept to a minimum.

Do not use abrasive cleaners such as:

- Solvent based window cleaner
- × Industrial strength cleaner
- ✗ Powder based cleaners
- × Scouring pads or harsh bristle brushes

Always test a small discrete section of a frame to confirm the suitability of the cleaning agent used. This will ensure minimal or no damage to the powder coat colour or surface.

VENTILATION

It is the responsibility of the owner to control moisture and air flow within their home. Please ensure there is regular air flow through the home to avoid issues with condensation and mould.

The exhaust fans in the bathroom and laundry will assist the removal of steam and humid conditions, prolonging the life of the interior finishes.

Leaving a window within your home slightly open will increase the air intake and efficiency of all the internal exhaust mechanisms (including kitchen rangehood) and will aid to minimise any naturally occurring condensation.

To ensure adequate air flow into the laundry exhaust, leave the laundry door open while the dryer is in use and the exhaust fan is on.

STONE BENCHTOPS

The stone featured in your home is a "zero" crystalline silica product that complies with regulatory changes and has been selected for its health benefits, better indoor air quality, warm character, durability, aesthetics and high quality.

The base of the reconstituted stone, being a natural product retains a degree of porosity. However, simple protection measures are the most effective way to ensure the natural beauty and stunning appearance is maintained.

 Use a chopping board, place mats and coasters to protect the surface from scratching, dulling or heat marks.

- Avoid sitting or standing on the benchtops of kitchens and vanities. Wipe up spills immediately, to avoid potential absorption of substances into stone.
- Pay particular attention to substances such as soap, detergents, abrasive or harsh chemicals or cleaners, solvents, cooking oils, toothpaste, tea, coffee, alcohol, vinegar and citrus juices as these may stain, etch or dull the stone. Lipstick, industrial and laundry marker and ink are unlikely to be removable. Avoid resting steel or items which may rust on the stone, to prevent rust markings.



 Do not use acids, wax, sealers, steam cleaners or petroleum products on stone.

Stone in all benchtops is not sealed, as any protection provided by a sealer is not permanent or absolute.

To clean, wipe down after use with a soft dry cloth, or use mild soap with lukewarm water, rinse well with clean water and dry. Do not use abrasives or scouring powders / cleaners (such as Jif, Ajax or Gumption). Heavy use of cleaner may take off the stone surface gloss.



TAPWARE

To prevent damage to the protective finish, avoid cleaning taps and spouts with harsh chemicals. Clean with warm soapy water, rinse well and dry with a soft cloth.

To maintain tapware:

- clean tap filters every two months; and
- check tap washers every two years and replace as necessary.

A licensed plumber is required to undertake any works.

PAINT

As paint colour may change subtly over time, and paint manufacturers may alter colour specifications, we recommend any future painting be based on colour matching a paint sample rather than using the original specified paint product. A paint sample pot has been provided at handover for any minor touch ups that may be required.

Most marks can be removed with a clean damp cloth. Use a diluted sugar soap mix if necessary. Avoid excessive 'scrubbing' and the use of scourers of any type, as this may alter the finish of the surface.

CUPBOARD JOINERY

All Joinery surfaces are laminate. To clean and maintain, follow these quidelines:

- Remove soiled particles from surfaces or light stains with warm soapy water and a soft cloth, or a non-abrasive spay and wipe cleaning agent;
- Do not use abrasive or alkaline cleaners and ensure that the finish does not remain in contact with hypochlorite bleach, mineral acid, dye or iodine solution. silicon-based cleaners, polish, steel wool, acidic and alkaline materials. (Note that silicon cleaners render surfaces unsuitable for re-coating);
- Ensure all spills are cleaned up immediately with a damp cloth and dry off, to prevent swelling or damage;
- Buff out minor fine scratches (note the gloss level will diminish);
- Check, tighten and adjust hinges every six months; and
- Do not apply oil or grease to any joinery hardware, such as hinges, runners. etc.

STAINLESS STEEL KITCHEN SINK, LAUNDRY TUB, TRIMS, ETC.

To clean wipe with a soft damp slightly soapy cloth, let it dry and wipe with a dry cloth. Always wash with the grain of the stainless steel, to avoid scratching.

To protect from staining after cleaning with a chemical cleaner or coming into contact with food acid, wash down with fresh water.



SANITARY WARE

To preserve the polish surface of your toilets and basin, clean with a soft cloth and warm soapy water or a liquid cleaner to wash away any oils or soap residue. Ensure any selected cleaning agent does not affect any adjacent stone or tile.

Do not use powders, pastes, crème cleaners, thinners, window cleaning sprays or dry-cleaning fluids, etc. Stubborn marks or fine scratches may be polished out with Brasso.

CAULKING AND SEALANTS

All caulking and sealants have a limited lifespan, and it is the responsibility of the owner to ensure a maintenance plan is established to regularly check all caulking and sealants.

To maintain the integrity of the caulking and sealants the owner must ensure they are free of dust and debris and are not subject to extended periods of water pooling.



TILED SURFACES AND BALCONY

To clean, use a mix of warm water with a mild detergent. When dry, buff with a dry mop or woollen cloth. All sealants and caulking including external elements, should be replaced immediately by a qualified tradesperson at the first sign of deterioration. Failure to maintain caulking and sealants may result in water ingress that could cause damage to fittings / fixtures. This will need to be checked every 12 months.

EXTERNAL PAINT

Depending on location and exposure, re-coating of painted areas should be carried out every as per the manufacturers recommendations. The life of the paint may be extended by keeping it clean and not allowing vegetation, planter pots to be placed against it, or trees to rub against the surface.

In accordance with the paint specification and warranty, all painting repairs and maintenance must be undertaken by experienced tradespeople only, and appropriate measures must be taken for safe working areas and any external scaffolding.

GROUND CONDITIONS

The immediate ground conditions around your home will impact the performance of the house slab and foundations.

Owners should avoid excessive watering of garden areas immediately adjoining the slab as the presence of water is likely to cause performance issues with the foundations.

Owners should complete regular inspections to ensure plumbing systems are operating correctly and not leaking and causing continued / excessive wetting of the ground adjoining the home.

Owners should engage the necessary professionals to complete any excavation works in proximity of the house slab.

ROOFING MATERIAL

The roofing material should be kept clear of tree litter and debris which could fall into your gutters and block drains. To preserve your roofing material and prevent water ingress, it is recommended a roofing plumber engaged yearly to clear litter and debris from your roof and gutters as well as conduct a visual inspection of flashings, sheets, seals and downpipes.



HABITAS | Handover Guide | 28

METRICON **HANDOVER CHECKLIST**

It is essential that all care and maintenance is carried out in accordance with Warranty and Maintenance Guidelines. It is the owners responsibility to carry out the necessary maintenance on their home on a regular basis.

Your builder will not be liable for any issues that relate to, are caused by or contributed to by an owner's failure to carry out necessary maintenance as required. Failure to carry out necessary maintenance may result in warranties being voided.

Your builder's handover guide aims to provide a helpful guide on the cleaning and maintenance of your home, which can be carried out safely and easily, but is not an exhaustive list of all maintenance required to your home.

In all instances you should refer to the product manufacturer's cleaning and maintenance guides which are included in the Aurora USB as part of your Handover Pack.

Any activity that requires work to be carried out where there is a potential fall risk must be carried out by a qualified tradesperson in accordance with all relevant legislation, codes and guidelines.

In all instances you should refer to the product manufacturer's cleaning and maintenance guides which are included in the Aurora USB as part of your Handover Pack.

TOWNLIVING



HANDOVER CHECKLIST

Client name	
Building address	
HANDOVER CONTENTS	
Product review	
Refer a friend incentive flye	r
COMPLIANCE CERTIFICATES	
Development Victoria USB H	andover Guide
Plumbing certificate - drains	3
Plumbing certificate - sanita	ary
Plumbing certificate - fascia	gutter downpipes
Electrical certificate - presc	ribed
Electrical certificate - non-p	prescribed
Insulation certificate	
Termite certificate	
Waterproof certificate	
Glazing certificate	
Plumbing owner letter	
MAINTENANCE	
Timber floor care sheet	
Essastone / Caesarstone m	aintenance card
Stone benchtop care declar	ation
CSIRO foundation maintenar	nce & footing performance
3-Month maintenance form	
Alarm manual (if applicable)	
SMEG flyer (if applicable)	
CCTV footage of stormwate	r & sewer camera inspection
PERMITS & INSURANCE	
Building permit	
Occupancy permit	
Homeowners warranty insur	ance certificate
KEYS	
Door keys	
Garage remotes & manual	
Sliding door	
Window keys	
Letterbox key	
Client signature	
Client signature	
Date	
Dato	

	TICK IF RECEIVED
	TICK IF RECEIVED
	TICK IF RECEIVED
	TICK IF RECEIVED
QTY	TICK IF RECEIVED

3 MONTH MAINTENANCE FORM

Please list any items and return to Metricon office no later than 90 calendar days after settlement. Please email form to <u>TownLivingWarranty@metricon.com.au</u> and we will be in contact to arrange inspection.

Name:				
Property address:	Lot:	Number:		
Street:			Suburb:	
Contact numbers:				

Settlement date:

Maintenance period expiry:

THE FOLLOWING ITEMS REQUIRE INSPECTION

4	
1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
-	•

22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	

Client:	
Date:	

TOWNLIVING m

501 Blackburn Road Mt Waverley VIC 3149 **P** 61 3 9915 5555 **F** 61 3 8588 6956 www.townliving.com.au

Dear Homeowner

Welcome to your new home!

We have provided a completion pack to assist you as you settle into your new home.

We encourage you to file these safely for future reference.

In your completion pack, you will find:

- Occupancy permit
- Certificates for your new home
- Home Warranty Information
- CSRIO Foundation Care Guide
- Supplier Care and Maintenance Brochures

In addition to these documents, we will provide you with the keys to doors and windows, garage remotes and Air conditioning remotes where required.

Please note that TownLiving have conducted an extensive quality assurance program throughout the construction of your home.

Congratulations again on your new home.

Yours sincerely TownLiving by Metricon

TOWNLIVING is a division of Metricon Homes Pty Ltd ABN 55 201 276 124

Occupancy Permit





Certificates

Home Warranty Information









NEW HOME SERVICE

TOWNLIVING M

Please refer to the guidelines below:

Item	Items covered by New Home Service		
1	All of your appliances are covered by the manufacturer's warranty. You will need to contact the manufacturer directly so that repairs can be fixed under the statutory warranty. TownLiving by Metricon holds no warranty on your appliances.		
2	Storm damage – damage caused by storm and tempest is not covered by TownLiving by Metricon's Guarantee. This should be referred to your insurer.		
3	It is the responsibility of the property manager/owner to ensure maintenance of drainage including balcony wastes and gutters. TownLiving by Metricon will not be held responsible for flooding as a result of blocked drains (leaves, dirt etc.).		
4	Movement due to normal shrinkage and settlement does not constitute builders maintenance.		
5	When touching up paintwork is required, every effort will be made to match existing colours.		
6	You must make your home available during normal business hours for us to complete any repair works and we request that you keep children and pets away from tradesmen when at your home.		
7	If you have any building warranty issues please contact: TownLiving by Metricon on: <u>TownLivingWarranty@metricon.com.au</u>		



T 1300 METRICON (1300 638 742) metricon E Townlivingwarranty@meticon.com.au metricon.com.au

Handover date: _____ Property Address: _____

Please submit this form to Townlivingwarranty@metricon.com.au

Please provide your preferred contact details: Owner: _____ Mobile: _____ Email: _____

I/We believe the following item requires attention by the builder and request that they peruse the list and arrange to carry out the necessary remedial work:

	List Ite
1	
2	
3	
4	
5	
6	
7	
8	

Defects Liability Form

ems



Metricon Homes Pty Ltd ACN 005 108 752 ABN 55 201 276 124

501 Blackburn Road, Mt Waverley, Victoria 3149

T 1300 METRICON (1300 638 742) E Townlivingwarranty@meticon.com.au

9	
10	
11	
12	
13	
14	
15	
16	
17	
18	



Dear Homeowner,

Please be aware that prior to connecting your dishwasher and washing machine you will need to drill out the connection point attached to the waste located under your sink / trough (as per the diagram below)



If you are engaging a plumber to carry out the connection works on your behalf advise them prior to commencement as failure to do so may result in damage to your appliances and cabinetry.

Metricon homes will not be liable for any damage cause due to appliances not being connected to the waste point correctly.

Kind Regards,

Metricon Homes.

Client Signature: _____





T 1300 METRICON (1300 638 742)

To the Homeowner/s

New Home Service

Metricon Townliving is committed to ensuring the quality of your new home, and accordingly we would like to let you know about the process regarding our New Home Inspection and Service.

It is guite normal for minor items to require attention as a new home 'settles'. Therefore, we return after settlement to conduct our New Home Service Inspection. At this time, and in consultation with you, a member of our service department will inspect your home and advise what items require attention.

Prior to conducting the New Home Service Inspection, we will request you to identify any items you believe require rectification.

Naturally, normal wear and tear and household maintenance are your responsibility and will not be covered during the new home service period. The items not covered include, but are not limited to:

- Any marks or scratches to bench tops, floor coverings, cabinetry, basins, mirrors, glass, baths, showers or any other damage related items which were not noted on our QA Documentation.
- Movement due to shrinkage which is evident by minor cracking.
- Damage caused by storms or flooding. Please refer to your insurance provider • for claims.
- Fair wear and tear.
- Misuse or neglect by the owner. •
- Foundation movement due to abnormal moisture in soil conditions. ٠

Maintaining the home is your responsibility and includes, but is not limited to the following:

- Inspecting and if necessary, replacing tap washers
- Maintaining your home's stormwater drainage system by cleaning gutters, yard sumps and silt pits regularly
- Landscaping and maintenance of gardens
- Periodical maintenance of termite protection systems if installed with the home
- Periodical maintenance of ducted heating units and cooling units ٠
- Garage door motor and tracks

On receipt of your defect form, which you will find located within your settlement pack, a representative from the Service and Warranty department will contact you to arrange a mutually convenient time between 8.00am and 5.00pm weekdays to inspect and carry out the works agreed upon. They will also indicate the approximate timeframe required at your home to ensure we have time to inspect each item.



On arrival of your New Home Service Inspection, we will conduct an inspection of your home and allow for an agreed items list to be established. We will also take this opportunity to pass on some valuable information about your home that you may need to know in the future.

Following the inspection, our Metricon Service Trade will complete the general items which need to be addressed. If a Metricon Service Trade is not available in your area, we will arrange for any external trades to either attend during the service inspection or at a time arranged with you directly.

If we do not receive notification from you within three weeks after your 365 days of settlement, we will assume there are no items requiring attention, in which case we will deem our New Home Service responsibility to be complete.

We thank you for your cooperation in this matter and wish you all the very best in your new Metricon Town Living home.

Yours sincerely,

Service and Warranty **Metricon Homes**





501 Blackburn Road Mt Waverley VIC 3149 P 61 3 9915 5555 F 61 3 8588 6956 www.townliving.com.au

TOWNLIVING

SETTLEMENT	ADVICE – KEY	COLLECTION	AUTHORISATION	

Owners Name:	
Property Address:	
Name of Representative:	
Representative's Contact details:	
Statement	I/We authorise the above representative to take possession of the keys and property documentation on confirmation of settlement by the vendor's representative.
Signed:	
Date:	

To all Metricon Customers,

Service Connections - Electricity and Gas

HIA customers – There has been a gas and electricity account established with AGL, with the details you provided upon signing of your contract. At settlement of your home, Metricon will advise AGL to transfer details into your name and you will be responsible for all billing from day of settlement onwards.

10/90 customers – Upon completion of settlement and provision of keys, Metricon will arrange for a final reading of the property and close the account once the keys have been handed over. It is your responsibility to contact a Power Authority of your choice and set up a power and gas account in your name at the settlement of your home.

Failure to set up an account will result in accumulated costs from date of settlement being forwarded to you OR in some circumstances the power being disconnected.

Should you wish to change retailer, please contact AGL Customer Service and request a transfer to your preferred retailer - see below AGL contact details.

Thank you,

Metricon



Phone: 131 245





Termite Protection Warranty Activation

Dear Homeowner,

Please find enclosed Termite Protection Homeowner Pack.

To activate the warranty, please complete and sign the attached warranty registration form and return to relevant Termite supplier via post or email.

Please also note, the enclosed sticker is to be placed inside your meter box, where a record of inspection dates will be recorded following annual treatments.

Should you have any queries, please refer to the enclosed termite documentation for contact details and further assistance.

Kind Regards,

Metricon Homes

CSIRO Foundation Care Guide

The CSIRO document is designed to assist you when landscaping around your home and outlines key factors to take into consideration.

We recommend that you take the time to read this document and use it as a guide to identify causes of soil related building movement, and adopt methods of prevention to reduce the chance of cracking in your home.





Foundation Maintenance and Footing Performance: A Homeowner's Guide



B17-18 replaces Information Short 10/91

Buildings can and often do move. This movement can be up, down, lateral or rotational. The fundamental cause of movement in buildings can usually be related to one or more problems in the foundation soil. It is important for the homeowner to identify the soil type in order to ascertain the measures that should be put in place in order to ensure that problems in the foundation soil can be prevented, thus protecting against building movement.

This Building Technology File is designed to identify causes of soil-related building movement, and to suggest methods of prevention of resultant cracking in buildings

Soil Types

The types of viols usually present and/or the registed in land world for residential huddraps can be split into two approximate process granular and alay. Quartoften, form@com sold is a compare of body types. The general problems associated with sold having granular controls are morally cannot by erosom. Olay soils are subject to saturation and swell/shrink problems.

Choosing in a given ingressing generally be obtained by application to the local authority, but these are sometimes totaliable and of these excloselities generalized upon should be compressinged. As most balldings sufficiently proventient problems are founded on city with there is an employee or classification of justs according to the armount of swell and shrinking they experience with variations of water context. The table is how is Table 2.1 main Ari 2870, dor Residential shift and Forting Court

Causes of Movement

Settlement due to constructions

There are two types of sectionscire that occur as a tostill of construction.

- Instandante vottleeteent os vers velere a heilsleap is fiert placed on isy foundation soil, as a result of compaction of the joit under the weight of the scentore. The cohesive quality of the volt putquees against this, but granular (particularly sandis) soil as susceptible.
- Choosefultations repreferences a feature of play and and image take place necessary of the exposition of moving efforts the soil or because of the will value of reconstruct to local compression or shear acrosses. This will usually take place data ng the flast few enoughs after sometric term, has buy been sporter in take many reaction exceptional values.

These problems are the previous of the traildes and straid be taken rate consideration as part of the preparation of the are for construction. Building Technology File 15 (BLE 19) deals with these problems.

Erosion

All software prime terrension, but saidly soft is particularly susceptible to heiring washed away. Even also with a used component of say 10% of tensor cuts without four envision.

Saturation

This is particularly a predden in a day you's. Saturation creates a hoglike inspension of the sod that causes it to hole certifiely all of its bearing capterly. For a feasier depret, sand it affected by subaration because saturated satid may indeeps a reduction. It values particularly responded satid fill for hedding and blinding layers the west it this evenly object as itemachine settlement and should normally to the parcipal of of the big lifer.

Seasonal swelling and stronkage of soch

All class ceaes to the presence of water by slowly absorbing it, teaking the sud-converse in veheror (see rable below). The degree of encouve visios considerably hereoen dolfferent class, as does deside tepres of decrease during the subsequence drying out caused by for we obseperiods. Because of the low absorption and expulsion rate, this physicare and will not usually be outlocable unless decrease are prolonged ratery or dry periods, usually it weeks or months, depending on the land and wat shape remotes.

if ite swelling, it soil steates an upward lorge on the loorings of the booking, unit shronkape operates solutidence this takes away the support metaled by the footing to retain equilibrium.

Shear failure

This phenomenon occurs when the foundation weldkes not have sufficient sciencific to support the weight of the feature. There are two major post construction causes

- Septembrane loost increase.
- Reduction of Interal support of the will code: the instrug due to epictum accession into a
- To also such stream failure can be cauged by variations of the woladjustment to or unider the looting.

GENERAL DEFINITIONS OF SITE CLASSES			
Class	Foundation		
1	Most sind and rock sizes with inite or no ground movements from moisture changes		
\$	Sightly reactive day size with only slight proued in occurring from mousing changes		
M	Mederately reactive chysics sile sites, which can exprotence positioner pround innovement from monsure changes		
11	Highly reactive clay sites, which can expensive high ground inconcert from measure changes		
F.	Patternely reactive sites, which can expense our extreme ground moviment from moniture changes		
A IN P	Filled size		
Р	Sites which inside soft soft, such as soft chy or sile or loose tands, landst.p. mine subadence: collapsing softs, soft subj to prostrue reactive sites subject to abnormal measure conditions or soms which cannot be classified otherwise		

Tree root growth

Trees and shirths that on allowed to grow in the scaling of their type on growing for the point of converting in two ways

- Reserve bits grow index assumptional interaction of a consistent or all size, exchange a present reaction and pressure reaction and
- Roots on the vice my of frooting, will apport prove of the molecule involve to entrate the case of shorts again safety area.

Unevenness of Movement

The represed ground resources deviable distance and these are enserved through our the building's for noticion soll. Surface are devin concerns formations by maxim by concerns.

- * Differing congregation of found monishing previous operations
- · Data againstance constance from dation, soil prior to constructions

We serve a schematic mean a neuronalise schematic tensor wares postall. It was not an endermoise a floring that traverset the device can regard the family times have been traverse hap with adjustments. Forting that reacts is the same datactory is the flow

National set of the set of the solution of the weather where we taken wills a water of the markes water poind. In this leads solve over the event of the set of the solution o

Second swelling and shrinkage of classs of affects the predictor of the backforp first. One productly growts to the construct The swelling process with user by begin at the open discussory of the Fulding, or on the secondary solid where the first oction. Swelling graded by two less the instance of the shortprion constructs. Shronkage away where the the solid back is proteen.

Effects of Uneven Soil Movement on Structures

Fresion and saturation

Eresson removes the support from under Sourspaceouling relevant subspires and the support of the stress render wheth it extends. By theory with our hier or the stress ere ned by the removal of support by briefging the gap or current erebp and the bricks of the monar feedeing full. Older mesonry has had resonance, budence of history super constraints are not support on the rest and the protocol.

- Step cricking in the transition beds to dy affeld with a above between openings such as deors or windows.
- Vertical coulding in the bricks fusually but not necessarily in fact with the vertical body or perpended.

Is a result gluery affect of by a cosing one submitted of fract dations will extend only interaction on which can be acceptance suppose and only of the three line fraction that have lost the stopp of cost fractions are supposed with extension are supposed with the stopp of cost of the stopp of the stop

beasingly welling/shrinkage in clay

Swedding for inflation and all enorminal principality first fifty the most responding for inflation and all enorminate principality for the neuronality of the periodicinal tensoring optimizing and all enormality of the periodicinal tensoring optimizing and provide the building for optimizing first internal force ups. This sociality first trads to the optimizexist effect, first now the optimized for any sum product higher that it is entered of the latternal.

The first standards compare only be that the first spectra slightly insked, it is so that the output bod by state shorts and the state theory of the first sector in the ingenerative body states and states in the comparest spectra is being with the table table of party spectra is being with table table of party spectra. By so the first spectra is being at the hard stades of party spectra in the hard stades of the hard stades of party spectra is table tabl

As the project of the spinor process is a spinor dynamic to the intervention access the intervention of bottly spinor provides the fourth spinor between the row of the symptome wall is appeared to the spinor bottly spinor between the row of the symptome wall is appeared to the poly of the row of the swifting will be intervent to the poly of the row of the row of the spinor bottly and the row of the spinor bottly access the bottly poly of the row of the row of the spinor bottly access the row of the ro



As the verticle system is a pays politic will begin in thy isolating extended too maps will be first attented, beginning, with the loss toors where the constraints of susception. On this the effort of lower up the extended too maps. The downing is independent of and stacking reduces or decappears where it is operated because of decappear, that other courses a pairing. The roof does that because only at

Denoing and dobing any absolutes the two scentine in other ways, in areas where warrat, were summers and coaler day winners prevail, water tanguatans equily to be toward the interact and durating well be accorrented, where is winter an unners, the day and whereas the or d war, were congraded, enable of be cowned the accordance and the another bits grappensity to exact column.

Movement canned by the north-

In general, growing norts will excit an upward pressure on to othes, whereas will order to degree before or trees or structure statistic constraints will transto remove support from order footagy by inducing structure.

Complications caused by the structure itself.

Must because that the soft cances to be excited on orderative site errors all in the either open down. Mowever, because diese to certain solution spread evently around the factures, and because the building restors an even observation because of the up doty, forces are excited from our part of the building to another. The rule result of the base farses, showing meatineral. This resultion more international organization of a possible cancer deviable symptoms do not simply reflect the original cancer. A summany seriogram is funding of shows on the vertex membrane of the building.

Diffects on full massing structures.

Be-dwook will constructing where is can leaved accorption sporareas that to a volption fusion will subsolved foundations of tables, points, have therefore usual to see cracking at work protots, such as esprengy for workows in divide.

In the evaluation of construction a settlement, considing will accord vacuum index upped after the process or settlement has seared

With their second crocom, crucking will us a lower solution developone? the reagant's most have been to not observe in the subscience it is decapted a neuralised the effected parameter for one and the structure has subscienced on other teachers that to date effective

in the case is well shock end, exiting the knowle will provide conreturn to the original cost term that completion of a systel. It we set a to prove lakely that the continual effect will need to be solely exits a lass in solids about that brackwords and state of any hyperbolic the will result be forces enjoying to explore a new exception position. Uniterms that on a size, where swelling takes place effect constitution one erasising occurs, the conclusing takes place effect constitution one erasising occurs, the conclusing takes place effect constitution after the states segment of the case of place if the solely permatic events the proposition of the systems of the sole wild give the effect of the position of the systems of the sole of the sole of the events mean field with the backbased is give the sole wild give the propowide mean field with the backbased before your ally independent

With its period system once the creating is established, if there is no induced implications of estimated by the period one of visuality periods in the period on the period of the periods of the period of the per

V pleases, classed by growth at the tools of the horizing option a single version deal where of here was an dealy not the observe advaescin function for exchange to separate sectority of here cosofic international error ing his occurred.

The dotted istructural generation is don, the users but of teachwork in the evenual wells and an last some of the interval walls. Idependances for not type, corresponding load for multistenation on what any opporthous college and the for the supported to these case of its angualty visible cracking doins could be the manifolds. of attention, however there it can have each plessed speed and address current traffed to computers some supporting rate, to this should be Cacked if there is any dealer. In one case contractly would conlorg is preparate is a golds to surveys on the second generally and to broad also be remembered down to concord to the page becapable of supporting datasets set

Effects on framed spin, types

Converse shell framed bioldings the less black to reduce eaching and to well-shrink than manority enderings by my statistical Resolution. Also, the dot it ingelishing effects rand to be lawyer tacance. of the lediter weight is wally. The many take to fremest buildings are cocountered because or the solated pice to arising a tot made walks Whete crossivery saturation cause a first opticarill away, this can couble designing which a wall mass bridge. This additional stress carsteate cracking in wall lining operating when there is a weakposter the structure areal by a door or workey excising him. towayne indiversitiest fair and efficiency will be so streamed as prior film. status damage somme first tylabiritations of all of the above symptoms for a manadetable period. The same warring period should apply or the case of operand the should be noted, however, that where thermed buildings are supported by stop forecross done is only one (e). of Stokwark and therefore the externally visible walls are the supporting which its for the building. In this case, the subdivirmassions with our beimpected to behave its following with,

Effect) on brick series structures.

bisable the load bearing structure of a brick senser bathling is the frame that makes up the interior leaf or the sergonal walls play. prolops the approach wills, depending on the type of root, the building can be expected to believe as a transition is more theory does the external prayment will be have or a similar way to the external learof a full masenty oracian-

Water Service and Drainage

Where a water of some piper a survey or controlwants through processing the consistent's building is water trake, in cause crusion, welling or surgeration of susceptible soil. Even a still use of leak user or crough in consistent las translations. A leaving tap many building can have the structflext. In addition, treacher continuing processing become waterconcess evid thoogy has dilled particularly where broken rubble to tool as fill. Write that treas a neg development here an isrespectively the weaks contained and strain repage into subfloct team ว่าซึ่งเหมล์ของ

Pipe halongental tools havater those also memoryly there as J stephmust in the source of water complexing and exacerbaring the poblicar

Distribution and an evention type volume of winwater beaus concentrated in a small area and

 Intotics) talk as not gettering our cosh in overflows its race. potters blocked with has as each

- Corrocled gatteeing at downpipes carry oil, water to privatel.
- Descaping and parameter open ted to a proper stormwater. collection when will down a concentration of where to sole that is durally adjacent to boundly, sometimes causing large scale. problems with averasion saturation and magazion of water module dar bestörne.

Seriousness of Cracking

In general, prost can king to and the paper in work is a constant of maximumly and can be keption option or even removed. The table below is a reproduction of Table CT of AN 28-0.

AN 2870 also publishes figures relating to catching an conjugate flow is however because will cracking will remailly teach the critical pieces optotiskath carbor than chacking in Cabs, this adds to not reproduced here.

Prevention/Cure

Plumbing

When balency nown upp is coused by water service, not plasmingsever or stratopater taking the reardy is on option the preliferer It is paid on, however, to consider it's thereating pipes away from the buddling where possible, and relucating tape in postenior where any kukige will not due to water to the building violative twee where pully traps are present, three is sumerimum sufficient spiller creater. convolution succession particularly or modern invaliances in agsmaller diatereter PVC fistories. Indexd. some publy maps are not studed directly under the apsorbutiare invalid to charge them, with the result that water from do tap may every the backfilled toroch that tomes the sever piping. It the trench has been poorly backfilled, the water will either groud or flow a ong the boycon of the trench. As down treaches usually num thrapsafe the proteings and can be at a similar depth, it is not hard to see how and write philes. (b) side to red attoor a strench care easily affect the dramitation's ability trasupport forcings or every generative and constituent and

Ground drainage

In all such there is the capacity for ware no travel on the surface and bill wire. Surface water flows can be established by inspection during and after become profession care. It as even a proof dryin machcounseled to the stortswitter collection system to itsually as each so laterate.

it of however, som zones necessare when attempting my ascentwater to guriese that testag be carried on the establish whereastly Upglicane wave locations. This rabies to reserve to in BCT 391 and true properly be equirable concurs to comprise consultant.

Presection of the building perimeter

It is exercise to reconcider that the well that allocity to those ups exercise. we Depoid the school hubbing line. Warwing anguiden plantsslotally and trees causes when of the most second when problems.

For this record paragebric where problems exist on an Defaultoccur of its to accounted that an appracht property beneral of anothe as make of the pullding behavior as necessary. This asserge

Description of typical damage and required repair	Approximate mark width Sintit (see Note 3)	Damaga Category
iHarran, sea ks	(0.1 mill)	n
E to otzako which ito mu point repair	Lino	
Conservation for burylasty Circl. Deors and windows stack or gluin	- i can	2
Free sy can be reported and provenly a site functional of evaluation for the formation of the second standard windows work. Service paper can fracture. We identify these often imputied	 5. EVen in the animum beautiversity strain of these inverse principal 	5
Eventser report south insuls top the thing has and reporting, sections of south- especially sister to ussue dwinn ows. We take with done through decret, Walls location to budge a uncealing south loss to the ong to bear is, between preventing ted.	 15:25 and bacalso depend an another of cricks 	



should exceed to us and a solution of the pression work with mantas, web and shi ald fixe in automatic fall away from the out dang of http://line/flastic/prising should be endest draw 1001 mentality back your tusts.

is is produce consistent dramage paper away the probability paying of perclision resort complete mix train furing trajage. It this is not print call of the tweatery possible of be replaced by PAN and broadillary denoted send the same net type reserve retransed by car and or minited to the some denorm

Experience and a second of water scattered in wase to remote appendix barrang accased telecate theory of many trent the his latery opposite days and actively have very back by E. (4).

in may be describe to restabling mediabation there avails only on the pavicipate de la della de la télez finalencie de que de la nagere maded these relationships had an for the souther of any

Confidenciation -

In buildings who contribute to the state where it mere and in our support doors as a sufficient violation creatis actual conditions for condensation provide the where the reachest of the ended devocation Roo das da ground Condeas non-acis or terminate Parantepresent and the edition and regards only survey are processed down groups out there does the adoption subtled with more special when an million and reacy realistable.

Warning Ale cogiet as Darking Technology file deux web or estimated large reducid be say that abelow most many which is a realizable or near the or the providence cherality

The information in the state of the second state of the state of the state of
The information by a diversity of each of manuse to mental and each
Former professional advice second statistical technology get
7.01.04m
CSIRO PUBLISHING PO 60+1139 C
La constante de

no states a construction for external tweet in double 2 a twent was easily of a model of the taward scripting nates endered ender die oberend operations. Iolingwood 2066, Australia 21 2002 2054 were a transmission . 11. . . . Cost and description of the second contract of the second cost of the

 Xare the concord income only need or under Unders. electronics and the definition of the first one of the new second s

 Halos allos accounts and provide contractor provident. visition and a to solve as performental agree or an and spalers. White any neuron feedback constraints to the forming and. wills the here with the data mate contraction we walked the "viais acts. Discontos as well as dumptess of glacific of Briaand cound to madenate periodially dates when a rebiopist wassept dynamics and neuro-

The garden

it to do by community or they have to plan shore oping a sany right within a manufactory or or net to the data angle project one reprint to departicip phone the docard traces prior has in-1.1.1.1.1.1.1.1.1

Overvaluating state to influence of algorithms watering systems is a constructs examinitization on and some impartion angle for pape, if a tratecryary to use these systems, it is affect that to remove yarden. ands to a cromeler centrate distance to estimatings.

Existing cross

Where a tier is couving a problem of soil drong is there is the ecoveries of thread of upperval of for anys. If the oriend agraphs are solisishing and the conclusion will not opplific radio during the costthe shorld be secred and a concrete or the distance placed. systematical prior the second processor to trace a subground can also discussions. the building. It is it as a possibly to armity obly relevant access without during to the fig. on application to monitor the my strend. be incide to the boat and away. A product point storp to sphere skelyornadate before they become a problem.

Introduction are incessible plants and shripby

State departments owes conjugated bart can provide a arionorganized asso parameters where in white meeted and she defance. from huldings of most queers. Bothing park, is an 20 conferentrationality for references in plan over the drains, or ballenge habe down it with

Inconstrain

Exactivity of an entitle to trap some of the postpacies requirement of the support of posterior posterior and the safety of a second of an engle of an a level the solit and in the two rate to termine study of 2 mistingly will called by important sevence incamp and cars, openformly between sulfayes and constants. Removal or sulf within the angle of a pose will three write it may

Remediation

When service investigation data has washed away sub-top a zerice. four approach of the same of isserver, or should be not obliged and comparized as the summarized where homegonaxy wear and reasonable gravitors to or other specialist work may be regional. Reparkation of hyperbolic torond money or generative here also of all steart statistions

Wang needed to the general initial become of sold Shank effect. comprovidentias by religion to allesi acido e borace by Ellerethe papification opposed activeness declaration and easy to within modong finadiage becaude what the rest we happened the each riseans, the extra conducting well pass the design around increasing the monitoring and the lower of the state of the second If the subcroacy to use how kings it streakflow as a paraset free. wedge to a more compression a creater our topogetly

This BTF was prepared by John Lower FAIB, MIAMA, Parmer, Construction Diognosis.

Supplier Care, Appliance **Instruction and Maintenance Brochures**





Worth doing, worth Dulux.



Worth doing, worth Dulux,"

dust and dirt will create not only a slip problem but also act as abrasive sing the floor to scratch and promaturely wear. A regular sweeping progr ds to be established to remove damaging particles. We recommend that ace is swept regularly, with a minimum of twice weakly sweeping with ar ice is swept regularly, with static map or fringe mop. as abrasives

Pa ā

In protoctor pads to the legs of chairs, lables and other furniture tent the floor from being scratched and to reduce noise. from being scratched and to reduce noise

water. Ensure the lended periods of time. placed in high use wet poviant to wipe up **sately** sesedind. pe up spills immediately on coated flooring even if the sp surface is clean and dry and do not allow spills to sit for fitme. Non-slip rubber mats and/or protective mats show wet areas to adjacent kitchen sinks and bathrooms for and additional l floor protection

2 8 na wax the

lloor

- wel mop the floo
- not use a steam dow
- Avoid spiked heel shoes pebbies, sand and other ábrasive materials
- Oo not use stoel wool or scourers on the figor,

<u>_</u>|_|.

- Do not use non-recommended scap or detergents withe floor pour water directly onto the floor and nevei
- Do not use ammonia-based cleaners or mothylated spirits

rd not completely ding your timber floor, -ammend Loba coating maintonance coat day your engineered aml ing can not be recoaled). do have difficulty worn through. is required. locating Loba products products, your local sander The best ed. Maintenance coats are best as you ar a light built and one coat is required. We Ē 2 Your local floor Ч Cell time lo 000 1300 s please go to 137 055. g) this is whon your floor (sander will be able adv ya I need recoating (lamin a is whon your floor is will know where to i áre not > got thes ŝ ti 9VQ

Thomastown Head Office: 5 - 7 Strong Ave, Thomastown VIC 3074

T 1300 137 055 | F (03) 9460 6777 www.ptf.com.au

religious seven a sus pointer will with the text mapped in period based over the consection. temptet on to work it wild plateaver, havend, classified to provide a succeive American Large



Cleaning interior surfaces could in Low-Contro foi Delux pointwork in your Shenn to Mett \$15,5766

Dulux paint care guide

of your investment.

How do you extend the Site of your

converging interspective from

Looking after interior paintwork.

location representes in a particular par-

Environ process, which builted they show up.

constructions and grown in March and a

Next program by provide and the second

Classified approach and accelerate element

nest server up, without all hed relims.

exceeds all strike rewith painting from

we shall all or be preserved water or

be avale. Device we down in 6466 ew

be a sub-plan is near the Gravit strain.

Introduction to the set of events and a

So, if the tagets previous states was

weather and the state of the state of the

Went to the dealer onto by and West SWent

new hoose

par://work?

Crossient at

Approximate

The or wall between a protocol that that are that finds as point of convolution both size is a fight of the state of plant of the state of a very counterpart territory

Centerers above an arotenting your name with Dulux. We would like to offer space tips on record for the

painwork on your name so that you can extend the life of your paintwork and note in maintailing the value.

- 2. April 1988 and weather to we do not the remains the classifier's her bein dependent
- Agody means they test model and a reason. a solution, where the market upsil particular strategies
- 4. Movement was also yelless to the scientist. through way program through a symplectic way. diversely newsperies agreed with th constants fragments.
- set we grand a firle sweet independent state. approximate and the high
- The second second should be a second se observation low street substant. Avoid, suggests as and to be written have named and we are a second to provide a new the sufficience of cousing Annal 1951 we

Clean opiniterior surfaces copied with, lawsheen, semi gloss & ploss favishes.

- 1. Desthicked program of the Steepower there are part and
- A version system water, or the Plaprocess access. You can use a Jamp effort is an entrie lunch os Alexanderes Wij enroel op 5t geroed, wolf Vicences mony stablements as
- 3. Apply to the plotter map with a lot through the balance to work power the whole station with a mentioning one of dwife the

Cleaning exterior surfaces copied in Matt, low sheep, semi-gloss & gloss tinishes

Dulux

- Press e a élumentel ester servicitada. with game contrast manifold responses. Conservation and
- Apply to the relation builded under the profile destruction of the second s you with second deals with the dimension long the maximum attention of the second the right point of your between whiston a minimum and a single share of the
- glibelors the wall or photopolities solution the three paster is a dependent of nete the service on this theorem. water Princip to wells. Berlinson with to very oppic water producer a net croptly. summer to a summer the second states at ofruan entres cabisfal los averana su etc.
- 4. We stry may always any part was strong woversteing tentre instruction

Save your Duly's Touch-Up Point!

Spanner de la seu contra de pour o for unite She will be a formula part this new case contraction per plant the spectral solution. we the suscential provides for a second physical and a basis respectively two should be incoming of a writer because processor esercitor reference la purchas reclamant en entres

An incommence additing a commence with the show a state of the complete backet of the weavour mark brown tech-

Average a paint protecting over a new day ten here soll and the sector and all proof. which a general state to we will be case to Anna Isali -Cottly and

Preventer Future Castemar Service. Jonated 13 (27) 26

Bust Regional

Segnal Second

Worth doing, worth Dulux.

Concentration gradem Acta, Wei Alfred, Mathematical, Action and a registry of sciences. Productional ية Philosophy (Association of places of personal sectors of the sector of sectors of the sectors of the sector



Perfect TimberFloorsⁿ

act Timber Floors et Timber Floors only sell and recommend Lobe Herdwood Roor cleane Domestic floors only mmond you only extends 1ber 170 set up a regular maintenance progr the life of the floor but enhances its to following care and maintenance: care E

5,0G

• biggest challenge for coated timber floors is dirt and grit particles ked on the floor, causing an abresive sanding effect. This greatly in wear of the surface. First point of attack should be to have proper turing mots at all entrances thus minimising the amount of damagi fictios, gnit and dirt, being carned on to the floor. Keep doormats we t panicles (greatly inc incre gril æ Б

Great care should be taken when moving and placing furniture. Furniture should be lifted and placed, not dragged or pushed.

ashing of sealed floor clean, shiny and safe a use of harsh detergents is not s wi∎ void your wa⊦ranty. Loba 0 oer floors. 5 ations. ted cleaner d cleaner is designed the removal of grime. spok [his icifically formula This PH neutral, formulated to s Gan enh enhance its appearance ĝ concentrated, blode hancing 8 Care haş Coommended nor is it necessary Care has a PH neutral floor cleanor VilueB (tha floors but effectively de and ВЛ beauty. ŝ, II kee

DON'TS



🟫 glass splash backs 😭 mirrors & more

Fremulation vector a Poxil Id TW AB Visional 1987 yrs Head DS the experitor North all E Oxford Road Lawerton North 3026 PO Son vid St Aftern Vectorie gear Photol (no) 4504 Cox Fax (14) 4594 CV/L W Weight TK, TIN, Com Ap

April 2016.

Splashback installation, Care and Maintenance.

Premium use quality materials in the manufacturing process of your splashback and within accordance of Australian Standards.

Please take note of the following:

- Splashbacks may be subject to colour variations conditional in different light conditions, this is due to the iron content in the glass.
- Breakage cannot be a process of warranty, as it can be due to impact or spontaneous breakage. Spontaneous breakage is a very rare occurrence which is caused by the formation of nickel sulphide (minute impurities in the glass) which occurs in the manufacturing process of all toughened glass. No toughened glass can be guaranteed against spontaneous breakage.
- Recommend the product not be installed next to a high flame cooking area as this may cause paint to discolour.
- Gas burners less than 140mm from centre of burner to the glass and utensits "resting" against splashback will void warranty.
- Utensils (saucepans/woks) need 25mm clearance from glass for ventilation. Non adherence will void warranty.
- Prolonged cooking at extreme temperatures can still cause paint burning discoloration.
- Silicone is applied to all edges for sealing, expansion and contraction. The use of strong chemical cleaning agents may cause discolouring of these seals.

Maintenance and Care

 All glass surfaces should be kept clean by prompt removal of all dirt or grime. We recommend using an All Surface Cleaner and a non-abrasive soft cloth or paper towel for cleaning your coloured Glass.

SPRINSVALE

α, ός ε Ρητισκή η ο τηγογή Δρητηφιοία (τηγ) Ρητισκή (αχλημική) είναι Γιακή το τη ή ςαριατική

SEE, GNG

es Holongson Street Christig West Jones Phanes (ost) geographi Han (og) geographi

65N0 20

68 dena tek Schnet Eszonya East (554 Phone (155 S203 7595 Hez Tag) 5447 6800

ACEURY

etys Brune Critert A bark NSW abus Frome Try: Grassissis Frantos) Soggississi

9 steps to keep your Dulux® AcraTex® Acrylic Texture Coating looking great

The exterior coatings on your home should be cleaned on a regular basis. This will help maintain your coatings aesthetic appearance and preserve your Dulux AcroTex Texture coating system. Cleaning on an annual basis will remove light soil as well as grime and antiborne pollutants. Coastal exposure will have a build up of salt contamination and a six month wash down is recommended. All joint scalants should be regularly checked to ensure no cracking is evident, sealant will need to be replaced immediately.

The exterior can be cleaned with a low-pressure water. blast (less than 450psi) using a lanjet of cold water at a 45 degree angle from the wall (notperpendicular). The fan of the water blaster should be kept a minimum of 30cm from the surface of the Dulux Acrollex Texture coating in order to avoid damage. Alternotively you can clean the exterior walls with a solution of detergent and warm water using a soft brush.



B Localised grime or ingrained dirt should be removed by cleaning with a scrubbing brush along with a solution of detergent and warm water. Under no circumstances should you attempt to remove heavy staining using a high-pressure water blaster.

Check for cracked, loose or missing sealont as part of your regular maintenance inspections. You will find sealant in most areas where different substrates meet ie, above door openings 8 windows, pipes, where walls meet the soffit line and where electrical fittings and handrails have been ottached to walls. Control joints should also be inspected as part of maintenance inspections. All deteriorated or damaged sealant should be removed and replaced as soon as it is opparent. We recommend that a paintable polyurethane sealant be used.



5 It is important to monitor areas that are heavily exposed to the elements such as parapets and balcony handrail tops. Due to the minimal slope on these areas it will tond to hold dirt and grime which can potentially lead to mould over time if not regularly washed. These building sections should also be checked for any movement over time due to the extremes of thermal movement so it is critical that they are inspected and maintained.

Tomporary repairs can be made to cracks by Elling them with ablyurethane pointable seafant until the inspection has been completed and permanent repairs undertaken.

Buring your inspections dan't forget to check areas that are culd and dark such as behind heavy foliage. Dirt provides the perfect nutrient for mould and algae growth. The finy roots that these arganisms use to aling to your walls will cause your texture coating to deteriorate very quickly if not regularly cleaned.

Recoaring is recommended often a minimum of 7 to 10 years to rejuveriate the surface appearance. This can be done by using *Dulux AcraTex* elastomeric top cost protective inembrane to a selected *Dulux AcraTex* colour which will protect from air pollutants, water ingress and duit accumulation to provide a new low maintenance surface.



Any damage to the texture coating needs to be recoated from edge to edge of the effected wall area to ensure texture and colour consistency. If accidental domage occurs please feel free to contact your local Dulux AcraTex representative or phone Dulux AcroTex Customer Service on 13 23 77 and they will provide the support or technical expertise required to help solve the problem. Visual cracks may indicate underlying structural problems; a professional should always inspect them.



How Acrylic Texture lasts longer

Care & Maintenance Guide Exterior hada tel

When specifying a new project, insist on FLEXIBLE ACRYLIC TEXTURE, not just painted cement render.

The AcraTex 3 step system encapsulates the walls in a membrane envelope acting as a barrier against adverse weather conditions for years longer than coment render.

Available across the full Dulux* Exterior colour range.

The AcraTex System with it's **Bexible Acrylic Texture cooting** guards against degradation. Ordinary cement render is hard and brittle leading to typical problems like these.



CRACKING

Corport shrinks as it hardons & expands/contracts with temp. Low build paint systems are typically unable to bridge render cracking.



EFFLORESCENCE Sall blooming over the surface & concentrated

booching of cracks can occur. looding to discolouration and patentially pealing.



STAINING Inferior paint systems hold dir & can allow moisture ingress. Moisture attracts and mognifies surface contaminants.



Suitably prepared masonry substrate irefer to AcraTex system guides for detail)

AcraTex AcraPrime

More than just a "first coat" AcraPrime consolidates the substrate providing a stable base for long term integrity.

AcroTex Acrylic Texture High Build Acrylic Texture up to 40 times thicker than paint, providing feature style and Acrylic Texture durability with colour integrated throughour.

AcroTex AcroShield®

Elastomeric Barrier coat protection up to 3 times thicker than point - AcroShield Advance is the system lock that ensures maximum resistance to the elements and extended system life cycle.







Better looking, longer lasting protection

in future contracting in acrotex compu-[5] a 11 of sources of A 13 23 77

Dukat[®] ActoTex[®] is a division of DukaGroup (Australia) Py Izd. ABN 67 000 049 427. Dukat[®], ActoTex[®] and ActoShield[®] are registered itade marks and ActoPhime™ and Coventry™ are tode marks of DukaGroup (Australia) Py Izd.







Performance Coarings for Wassers



Welcome to your new Metricon home!

APPLIANCES & WHITE GOODS WELCOME PACK TIPS, TRICKS & WARRANTY DETAILS TO HELP YOU FEEL AT HOME AS SOON AS POSSIBLE







WELCOME PACK

TASK

Setting t

Note: Please produc exact fi are rele

household with real human needs

THE FOLLOWING TIPS ARE DESIGNED TO MAKE COOKING YOUR FIRST MEAL IN YOUR NEW METRICON HOME AS EASY AND TASTY AS POSSIBLE

	MODEL	PROCEDURE
he Time	Sôlt Ovens	• When the oven is first o "12.30", a beep will sou
		 Press the "+" and "-" b "Timer" () function b
		The minutes will now b minutes. Once correct,
	InAlto Ovens	• Once the oven is conne
		• The clock can now be s
		• The hour display will sta
		 Press the ► button aga
		• Use the + or – buttons
	InAlto Upright	• When the upright cook
	Cookers	• Press + or – buttons to
	Teka Ovens	• When you turn on the o
		 Set the clock by touching You will hear 2 beeps compared
		• To change the time, pre The current time will th

COOKING FUNCTIONS

Prefer to your but to see the unctions that evant Sôlt Ovens				
InAlto 60cm Ovens ☆ Light InAlto 60cm Oven ☆ Grill + Fan InAlto 90cm Oven ☆ Light & Upright Cookers ☆ Light Image: Cookers Inalto 90cm Oven InAlto 90cm Oven ☆ Light InAlto 90cm Oven Inalto 90cm Oven InAlto 90cm Oven Inalto 90cm Oven <td>ct to see the functions that</td> <td>Sôlt Ovens</td> <td>_</td> <td>6</td>	ct to see the functions that	Sôlt Ovens	_	6
InAlto 90cm Oven & Upright Cookers ☆ Light ImAlto 90cm Oven & Upright Cookers ☆ Light Image: Cookers Image: Cookers Image: Cooker	evant	InAlto 60cm Ovens	🔆 Light	[
InAlto 90cm Oven & Upright Cookers : ∴ Light [] Image: Second stress			S Defrost	
& Upright Cookers			Ϊ Grill + Fan	
Image: Const of the second			-Õ- Light	[
Teka Ovens O Fan-forced		5	Defrost	[
Grill			🐺 Grill + Top + Fan	ł
		Teka Ovens	e Fan-forced	2
Eco Mode			Grill	`
			Eco Mode	

At Residentia Group we proudly offer a comprehensive customer care program and warranty service

WE SEE THE VALUE OF PROVIDING EXCEPTIONAL SERVICE TO OUR CUSTOMERS AND MANAGING OUR AFTER SALES SERVICE IN A TIMELY AND EFFICIENT MANNER

SÔLT, INALTO, TEKA & ELICA ARE PROUDLY DISTRIBUTED IN AUSTRALIA BY RESIDENTIA GROUP

Customers can use our self-help portal to find a solution to their query or raise a support request online. Alternatively, this can be done through Facebook, Twitter or email.

Furthermore, our call centre operators are on hand to troubleshoot any specific product issues or in the rare event of failure, organise an in home visit from one of our service agents.

Telephone 1300 11 4357

Email support@residentiagroup.com.au

Online Portal www.support.residentiagroup.com.au

solt.house inalto.com.au teka-appliances.com.au elica.com.au residentia.group

Websites

Showroom & Postal Address 165 Barkley Avenue, Burnley Victoria Australia 3121

WARRANTIES

BRAND	COOKING	DISHWASHERS/LAUNDRY
Sôlt	2 Years	2 Years
InAlto	3 Years	3 Years
Teka	5 Years (3 + 2 on registration)	3 Years (2 + 1 on registration)
Elica	5 Years	N/A

HANDY TIPS

MODEL	PROCEDURE	
Sôlt Ovens	• To use the oven in manual mode (not using the Programmable Timer*) the 🏠 symbol must be aligned with the reference mark on the control panel.	
	* Note: The Programmable Timer controls the point of time at which the oven shuts off during cooking. To use this feature, position the timer knob (the centre knob of the three) between 10 minutes and 120 minutes. At the end of the programmed length of time, the timer will sound and automatically turn off the oven.	
InAlto Ovens	To operate your InAlto oven simply select the required temperature and function (make sure to only turning the function knob clockwise). Now press and hold the "Confirm" (▶) button for three seconds and your oven will begin to operate.	
Teka Ovens	• Symbol: Sindicates that the oven is transmitting heat.	
All Ovens	• Before using your oven for the first time we recommend a "burn off". This entails setting the oven to 200° C and running it for 30 minutes at this temperature. This removes any manufacturing greases and odours.	
	Please note: You should always keep the door closed with grilling.	

SÔLT





2 elica



SETTING UP OVENS OR UPRIGHT COOKERS

connected to the electrical supply, wait for the display to automatically show ound once and the "12" will flash.

buttons to increase or decrease the hours. Once correct, press the the button to confirm.

be flashing. Press the "+" and "-" buttons to increase or decrease the t, press the the "Timer" () function button to confirm.

ected to power, the LED display and "Oven On" (igcup) will be displayed.

set by pressing the "Confirm" (►) button. The ∎ icon will light up.

tart flashing and pressing the + or - buttons will adjust the hour.

ain, and the minute display will begin to flash.

s to set the minutes, followed by the ▶ button again. The clock is now set.

ker is connected to power, 12:00 will be flashing on the LED. p set the time or press \blacksquare to get into the present working mode.

oven, 12:00 will be flashing on the LED.

ing the + or – sensor.

confirming that the time has been set.

ress the + and – sensors at the same time.

hen flash on the screen.

Fan-forced	[•]) Defrost	🗂 Grill		
🗌 Bake	🕑 Fan-forced	🔄 Fan-bake		
Bottom Heat	Grill	📟 Grill + Top		
🕱 Grill + Top + Fan	🙆 Bottom Heat + Fan			
Bake	Fan-forced	🝸 Fan-bake		
Bottom Heat	🛱 Grill	🛱 Grill + Top		
+ Designates functions for rotisserie				
Maxi Grill	Bake	Bottom Heat		
Grill + Bottom	Defrost	Pizza		
🔺 Fan Bake	📅 Maxi Grill + Fan	🗵 Maxi + Fan + Bot.		



SÔLT, INALTO, TEKA & ELICA ARE PROUDLY DISTRIBUTED IN AUSTRALIA BY RESIDENTIA GROUP

Welcome home

Everything you need to know about your new Hebel home



Congratulations on your new Hebel home

The many benefits of living in your Hebel home

Congratulations and 'welcome home' to Hebel.

You've obviously spent many, many hours of considered decision-making in choosing your new home, its design, the look and colours, the fittings, the furnishings and so many other important aspects - and now you've finally moved in to enjoy the rewards of living in your own, well earned home.

No doubt, over the years ahead many things will change around you – its likely that your needs and your life-style will adjust as you also adjust to the changing world.

However, one thing you can rely on throughout the years ahead is your choice of Hebel as a sustainable, robust and clever choice for your new home.

We recommend you retain this guide for the duration of living in your home, as it contains all you need to know about maintaining your Hebel home or products that are so intrinsic to your comfort and peace-of-mind in the years ahead.

We thank you for your decision to include Hebel in your new home and we have no doubt that, for many, many years to come you'll love coming home to Hebel.

The unique Hebel attributes are best summarised with the Hebel 'tick' below:





HEB-2006 GECA 08-2005– Environmentally Innovative Products



Solid and strong as traditional bricks

Being a masonry product Hebel panels and blocks provide the solid feel, security and peace-of-

mind associated with traditional bricks.



Highly fire resistant for peace of mind and added security

Hebel is non-combustible and renowned for its highly fire

resistant properties. The Hebel Block and Panel Systems achieve FRL (Fire Resistance Levels) from 60 minutes through to 240 minutes (tested at CSIRO) and meet or exceed the requirements for all six Bushfire Attack Level (BAL) categories.

Another reason that when building with Hebel, you're building with peace-of-mind for your own future as well as the safety of family and friends.



A comforting thought for a comfortable living environment

Hebel's unique AAC construction provides superior

insulation qualities for a masonry product. The unique combination of thermal resistance along with thermal mass, make building with Hebel a smart choice for meeting Australia's stringent building regulations.

For home owners, the thermal efficiencies of Hebel has a two-fold benefit, reducing the reliance on heating and cooling appliances – the combined effects of using a heater less in winter and fans or air conditioning less in summer and warmer months, can have a big impact on rising energy costs.



A sound reason for better acoustic qualities

The unique AAC qualities of Hebel provide significantly reduced sound transmission

between rooms and noise penetration from external sources. Advances in entertainment technology (ie: home theatres) and increased requirements by homeowners for enhanced privacy in their day-to-day living make Hebel the ideal building material for modern homes.



Sustainability for a better world starts today

Hebel delivers a diverse number of environmental benefits over brick and concrete. In an

independent Life Cycle Assessment (the leading methodology used to quantify the environmental impacts of a product's entire life) undertaken by Good Environment Choice Australia, in accord with international standard ISO 14 024, Hebel was found to have clear environmental benefits across all key environmental criteria.

To be awarded the label, products must have a 30% lower impact than alternatives. Hebel uses 61% and 64% less embodied energy and 64% and 55% less greenhouse gas emissions than the comparative products, concrete and brick veneer. As environmental consciousness and social responsibility increases, Hebel is striving to exceed further to set new sustainability standards in building materials and residential living.



Proven in the market and backed by CSR

Hebel products and systems are developed in Australia by CSR Building Products Limited. With

CSR you can depend on product quality, technical expertise, warranty and stock supplies of Hebel products and systems.

Things you should know about maintaining your new Hebel home

Q: How do I care for the external surfaces of my Hebel home?

A: Hebel walls should be washed down as a minimum once a year with clean water. This process removes any dirt or other build up that has gathered on the coating.

Q: Can I backfill soil against the Hebel walls?

A: Hebel must not have soil backfilled against it. A 25mm clearance should be provided between the underside of the panel or block and finished ground level to eliminate moisture penetration.

Q: Can I cut a window or door opening into the Hebel wall?

A: In most cases it is possible to retro-fit an opening into Hebel walls. Professional advice must be sought to ensure the structural framing is suitable for this modification.

Q: How do I attach other external items to our Hebel walls?

A: A fixing guide (see below) is provided to assist you in selecting the appropriate fixing method for the object you are to secure to the walls.

Q: How do I drill penetrations into the Hebel for such things as external lights or speakers?

A: Holes can be drilled in Hebel walls using a masonry drill bit fitted to a standard (not rotary hammer) drill. Once the penetration has been filled with the required cables or the like, the gap around the penetration should be filled with a reputable flexible sealant such as Sikaflex polyurethane sealant.

Q: How do I repair larger damage sustained to the Hebel walls?

A: If the damage extends beyond the coating system and into the Hebel wall, professional advice should be sought to ensure the damage has not compromised the integrity of the wall.

Q: How do I repair minor damage sustained to my Hebel walls?

A: Surface knocks and scratches can be touched up with the same surface coating finish that was applied at construction (like any masonry wall). Ask your builder for details.

Q: What does "acrylic texture" and "full acrylic system" mean - I thought that it was render?

A: "Render" means; cement render, sometimes just painted with a thin paint topcoat. "Acrylic texture system" will incorporate a 1-2mm, noncementitious texture coat layer, applied over the render levelling coat and top-coated with a high build flexible finishing coat.

"Full Acrylic system" (eg Hebel PowerBase or PowerFinish[™]) means the system from the substrate up is an integrated, flexible multilayer polymer system (no rigid cement layer).

Q: Can I change the colour at any time?

A: Style and Colour are emotive and were most likely very important in your original design and colour choices. You can update at any time you choose (a great way to achieve a revitalized look for your home) or make that decision at your 10 year maintenance time.

Hebel recommends an acrylic membrane paint system of at least 150 microns Dry film thickness.

Q: How long will the coating system last?

A: Hebel coating systems are permanent. Like all surfaces exposed to the elements, preventative maintenance will keep it looking its best and preserve its optimum performance.

Q: Will I ever need to recoat?

A: Ultimate life-cycle costs of the total facade and finish are optimised when an Acrylic paint membrane (min DFT 150 micron) is applied every 10 years. This ensures the integrity of the weather proofing system and provides the opportunity to address typical longer term building maintenance issues - such as building movement.

Preserving your investment in Hebel is just one good reason, secondly a "10 year refresh" maintains the property's visual impact "as new" and adds to the resale value if, and when, the time comes to sell.

Q: What on-going maintenance do I need to do?

A: As a rule of thumb, you should wash the surface every year (more often in seaside locations). This not only removes surface contaminants but forms your annual inspection routine. Check other building related elements important to preserving your investment at the same time. Look for any areas of water ponding near walls, any loose or cracked sealant at joints and around windows, debris accumulated against walls, the state of gutters and timber, any signs of moisture under eaves - all elements that are routinely maintained and corrected early will extend the trouble-free life of all Hebel building elements.

Apart from its many other positive attributes, your Hebel home has been built to protect your home against the harsh elements.

Hebel has worked with leading coating suppliers, to develop high performance and long-lasting coating systems that adhere to Hebel's unique substrate – so it makes good sense to maintain the total façade system to ensure the finish looks good now and for years to come. To find out what coating system has been used on your home, contact your builder. Make sure you record the brand and colour specification of your top coat of paint for future reference.

To assist in the longevity of your Hebel finish, the exterior texture coatings on your home should be cleaned on a regular basis. This will help to improve your home's appearance and to preserve your Hebel coating system. Cleaning once every year will remove light soil as well as grime and airborne pollutants.

For best results, the exterior may be cleaned using a low-pressure water blast (less than 450psi) using a fanjet of cold water at a 45 degree angle from the wall (not perpendicular). The fan of the water blaster should be kept a minimum of 20cm from the surface of the Hebel coating in order to avoid damage. Localised grime or ingrained dirt can also be removed by cleaning with a scrubbing brush along with a solution of detergent and warm water. You should avoid attempting to remove any heavy staining using a high-pressure water blaster.

As part of your regular maintenance routine you should check for cracked, loose or missing sealant. You will find sealant in most areas where different substrates meet, including around windows and doors, pipes, where walls meet the soffit line (under eave) and where electrical fittings and handrails have been attached to walls.

Control joints should also be inspected as part of your maintenance inspections. Any deteriorated or damaged sealant should be removed and replaced as soon as it appears. In such cases, Hebel recommend that a paintable flexible sealant be used.

It is important to monitor areas that are heavily exposed to the elements such as parapets, and balcony handrail tops. Due to the minimal slope on these areas and the extremes of thermal movement it is critical that they are inspected and maintained. If damage occurs immediately contact your builder (if within the 7 year warranty period) or a leading paint supplier (such as Dulux) for technical advice. If cracks appear, this may indicate underlying structural problems and in such cases a professional should always inspect them. Temporary repairs can be made to cracks by filling them with flexible sealant until the inspection has been completed and permanent repairs under taken.

During your regular inspections don't forget to check areas that are cold and dark, such as behind heavy foliage. Dirt provides the perfect nutrient for mould and algae growth. The tiny roots that these organisms use to cling to your walls can cause your texture coating to deteriorate very quickly if not regularly cleaned.
We welcome your feedback and sharing your home story with other homeowners

Of course you'll be enjoying many social occasions and entertainment of friends and family in your new home.

But what about sharing your Hebel experience with other people outside your family or social set and helping their decision making?

That's where the so-called 'social-media' experience can really play a role in showing your home and telling your story to a much wider audience.

There are many people, perhaps similar to yourself who are currently choosing and agonizing over which finish is best for their home, brick or Hebel, timber floor, concrete or Hebel, what choice of boundary fence or what colour and kind of rendered finish they want.

As you know, these choices are never easy and you most likely did a lot of research before making your choice.

That's where you can now help people going through many of the same decisions and similar choices as you were.

So if you'd like to share your experience (and even your photos or movies) we welcome your input and feedback that might help others make the right choice for them in choosing their design, finish and materials.

Simply go to: www.hebel.com.au and upload your story or images.

Information you may need in the future

Fixings For Use With Hebel									
LIGHT DUTY UPTO 20 kg Eg Outdoor light fittings, taps, downpipes, other lightweight wall fittings				MEDIUM DUTY 20 - 50 kg Eg large light fittings, hot water services, clothes lines, hosereels, external wall fittings.					
Product	Type No.	Dia.	Length	Max Load	Product	Type No.	Dia.	Length	Max Load
Hex Head Screw 14-10x50mm	Type 17	N/A	N/A	11kg*	Ramset Ramplug	DNP12	12mm	60mm	20kg*
Hex Head Screw 14-10x5011111					namset namping				
	DNP8	8mm	40mm	11kg*		12/60	12mm	60mm	26kg**
Ramset Ramplug-nylon					Tox-YTox Plug				
Ramset Ramplug-nylon	DNP10	10mm	50mm	12kg*					
Powers Mungo Nylon Plug	MU8	8mm	50mm	16kg*					
Powers Mungo Nylon Plug	MU10	10mm	60mm	21kg*					

* Factor of safety (EOS) =4 ** Factor of Safety (EOS) =5

These fixings are available through selected hardware outlets and building suppliers around Australia

PLEASE NOTE- Items that cause vibrations or excessive loads to Hebel walls must not be secured to the walls, rather these items should be fixed to posts that are independent to the walls and do not transfer loads to the Hebel eg. -Gates, decks, pergolas, carports, basketball hoops etc. If in doubt please contact CSR Hebel on 1300 443 235.



Low rise Residential Systems (stick frame - up to 3 storeys) Hebel Autoclaved Aerated Concrete ("Hebel Products")

Who is providing the warranty	CSR Building Products Limited ("CSR Hebel"). This warranty is authorised - Andrew Rottinger (CSR Hebel) - Phone: +61299641775 - Email: arottinger@csr.com.au - 39 Delhi Rd, North Ryde, NSW			
Who the warranty is provided to	General publication			
Products to which this warranty applies	Hebel Products described above when used in low rise residential system For details of warranties on other products, or on Hebel building systems			
Commencement date	This warranty applies in respect of all Hebel Products purchased on or a current versions.			
Termination date	Until superseded. Please check CSR Hebel website for details of current			
Risks covered	Subject to the conditions and exclusions set out in this warranty docume materially degrade, corrode or break down during the Term of this warrant			
Term of warranty	20 years from the date of purchase			
Conditions	This Hebel® Warranty will only apply where:			
	(a) the Hebel® Product is handled and installed in accordance with CSR H ("Hebel® D&I Guides") and any other CSR Hebel manuals relevant to that			
	(b) no external forces or causes have degraded the workmanship and/or n Australia and or the relevant Australian standards regard the Hebel® Prov			
	(c) The Hebel® Product is coated so as to provide the minimum elasticity maintained so as to provide effective ongoing protection; and			
	(d) in circumstances where the Hebel® Product is used as part of a Hebel			
	(i) all components used in the Hebel® building system were specified and			
	(ii) the relevant Hebel® building system was constructed to comply with t and ABSAC Technical Opinions current at the time of installation.			
Consumer guarantee	These Warranties are in addition to other rights and remedies of the cons			
provisions	The following statement is provided where the Hebel® Product is supplied guarantees that cannot be excluded under the Australian Consumer Law. reasonably foreseeable loss or damage. You are also entitled to have the to a major failure.			
Exclusions	To the extent that the law allows, CSR Hebel shall not be liable for:			
	(a) Damage to Hebel [®] Products arising from external causes outside the 0 heating, pollution, exposure to conditions that would normally be deleter pressure, electrical or electrolytic damage, incorrect cleaning, neglect, fir vandalism, or malicious damage, industrial action, adverse weather cond the negligence or omission of CSR Hebel, and its employees or agents;			
	(b) Deterioration of any part of a Hebel® Product caused by work carried of			
	(c) Any faults to the extent that they are caused or contributed to by any fautached (including but not limited to the design of the frame or foundation			
	(d) Cracking in any coatings applied over any Hebel® Product (Note: Before to ensure that the coating system is suitable to the Hebel® Product subs			
	relevant Hebel® D&I Guide)			
	relevant Hebel® D&I Guide) Other than as expressly set out in these Warranties, and the warranties			
	relevant Hebel® D&I Guide) Other than as expressly set out in these Warranties, and the warranties t Consumer Act 2010 (Cthl) and any other law, CSR Hebel excludes all othe guarantees. To the extent it is able to do so, CSR Hebel excludes all liability for loss a			
Nature of recompense	relevant Hebel® D&I Guide) Other than as expressly set out in these Warranties, and the warranties to Consumer Act 2010 (Cth)) and any other law, CSR Hebel excludes all other guarantees. To the extent it is able to do so, CSR Hebel excludes all liability for loss a a kind ordinarily acquired for personal, domestic or household consumption			
Nature of recompense	relevant Hebel® D&I Guide) Other than as expressly set out in these Warranties, and the warranties t Consumer Act 2010 (Cthl) and any other law, CSR Hebel excludes all other guarantees. To the extent it is able to do so, CSR Hebel excludes all liability for loss a a kind ordinarily acquired for personal, domestic or household consumption Subject to the rights and remedies of a consumer under a law which can Hebel, to: (a) the replacement of the defective Hebel® Product or the supply of equi (b) the replar of the defective Hebel® Product, or			
Nature of recompense Related warranties	relevant Hebel® D&I Guide) Other than as expressly set out in these Warranties, and the warranties t Consumer Act 2010 (Cth)) and any other law, CSR Hebel excludes all othe guarantees. To the extent it is able to do so, CSR Hebel excludes all liability for loss a a kind ordinarily acquired for personal, domestic or household consumpti Subject to the rights and remedies of a consumer under a law which cann Hebel, to: (a) the replacement of the defective Hebel® Product or (b) the repair of the defective Hebel® Product; or (c) payment for the replacement or repair of the defective Hebel® Product			
	relevant Hebel® D&I Guide) Other than as expressly set out in these Warranties, and the warranties to Consumer Act 2010 (Cth)) and any other law, CSR Hebel excludes all other guarantees. To the extent it is able to do so, CSR Hebel excludes all liability for loss a a kind ordinarily acquired for personal, domestic or household consumpting Subject to the rights and remedies of a consumer under a law which can Hebel, to: (a) the replacement of the defective Hebel® Product or the supply of equires.			



The above Product Warranty is current as at 1 January 2012. Please visit www.hebelaustralia.com.au for the latest version



d by:

ms as outlined in Hebel® Design & Installation Guide HEB1270, HEB1353, HEB1279 and HEB1282 s, please contact your CSR Hebel representative

fter 1/1/2012. Warranty is current as at 1/1/12. Please check the CSR Hebel website for the latest and

warranty.

ent, the Hebel® Products are free from any defects in manufacture and materials and shall not anty ("Hebel® Warranty").

Hebel's Technical Manual, Design & installation Guides nat particular Hebel® Product which is current at the time of use;

materials of the Hebel® Product other than those forces or causes which the Building Code of oducts as having been designed to withstand under normal conditions

& water ingress protection as outlined in the relevant Hebel® D&I Guide and such coatings are

[®] building system:

d sold by CSR Hebel; and

the relevant Hebel® D&I Guide, the Building Code of Australia and all relevant Australian Standards

sumer under a law in relation to the goods or services to which the Warranties relate.

ed to a buyer who is a "consumer" under the Australian Consumer Law: Our goods come with . You are entitled to a replacement or refund for a major failure and for compensation for any other a goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amou

CSR Hebel's control including but not limited to, building structure movement, welding or other prious to conventional concrete products (eg acidic environments), mechanical damage, hydrostatic ire, explosion, radiation, collision, or other accident, acts of God, wars, riots, civil commotion, ditions (such as, for example, hail storms, sand storms) and the like, unless the damage is caused by

out on the Hebel® Product after installation.

third party design or under-engineering of the building or structure to which the Hebel® Product is tions to which the Hebel® Product is incorporated or affixed).

ore choosing a coating system, it is the Builder's responsibility to liaise with the coatings manufacturer strate and that it provides the minimum elasticity & water ingress protection as outlined in the

that cannot be excluded under the Australian Consumer Law (Schedule 2 of the Competition and er warranties and guarantees with regard to Hebel® Products including all implied warranties and

and damage (including consequential loss) where the relevant Hebel® Product is a good other than of

nnot be limited, the liability of CSR Hebel under this Warranty will be limited, at the option of CSR

valent goods:

ating products or systems. Please see your coatings supplier for details of their warranty.

Ider, please obtain your proof of purchase then contact CSR Hebel customer service on 1300 369 448

the claim. CSR Hebel may require documentation supporting the claim to be provided





The better way to build

For sales enquiries or to be put in touch with a Hebel Builder please visit:

www.hebel.com.au

or call:

1300 4 HEBEL (1300 443 235)

Disclaimer

The information presented herein is supplied in good faith and to the best of our knowledge was accurate at the time of preparation. The provision of this information should not be construed as a recommendation to use any of our products in violation of any patent rights or in breach of any statute or regulation. Users are advised to make their own determination as to the suitability of this information in relation to their particular purpose or specific circumstances. Since the information contained in this document may be applied under conditions beyond our control, no responsibility can be accepted by Hebel, or its staff for any loss or damage caused by any person acting or refraining from action as a result of misuse of this information.

CSR HEBEL 112 Wisemans Ferry Road Somersby NSW 2250 Fax (02) 4340 3300

HELIT038Apr14

Hebel® is a registered trademark of the Xella group. CSR Building Products Ltd is an exclusive license of Xella. CSR Hebel is a business of CSR Building Products Ltd ABN 55 008 631 356. CSR, PowerPanel®, PowerClad®, Hebel Block®, PowerFlore®, Hebel Flore®, PowerFence®, PowerBase®, HighBuild®, are registered trademarks of CSR Building Products Limited.







Make savings appear out of thin air with a Midea heat pump



Features



piece unit incorporates a top-mounted compressor with compact footprint

Handy Controller

Providing intuitive

operation & helpful

functions such as temp

setting, timer & safety lock

Highly Efficient Produces significantly more heat energy than the power input; saving on purchased energy

Built in Frost

Protecting the condenser

from icing for complete

Protection

peace of mind

-20°C to +45°C 0

No. of Persons

÷÷

ĴĴ



Auto Disinfection[^]

Periodically heating the

to prevent the growth of

water beyond its set temp

An energy efficient hot water system such

as the Midea heat pump is a great way for

households to make substantial reductions

in their energy consumption and cost of

A heat pump provides a quick and easy

replacement of your old energy-hungry

CO₂ emissions by over 4 tonnes, and

saving you up to \$930* per year.

Applicable to HP280 model only.

Heat Pump Selection

Cold

170

280

280

HP170

170L

Capacity

Hot

170

280

280

HP170

Climate

Warm

170

280

280

To be used as a guide only - based on typical usage of 45 litres of hot water per person thoughout the day.

170/280 170

170/280 170/280





*

Power Outage

Memory Settings are retained in the event of a power outage

Smart Technology

USES UP TO

ENERGY

Harvest the free energy from our plentiful air to

heat your water with the advanced Midea heat pump from Chromagen. This renewable energy

water heating technology uses up to 65% less

energy¹ than a conventional water heater, whilst

providing reliable hot water all day and night.

AIR Heat Pump extracts around 4kW from surrounding air



Did you know?

only convert 1 kW of input power into a maximum of 1 kW of output heat.

Energy Efficiency

Did you know?

Water heating accounts for nearly a guarter of the energy use and greenhouse gas emissions in the average Australian home.



*Estimation based on HP280 (RSJ-23/300RDN3-B) STC's in Zone 3 under medium load, obtained from independent laboratory test results and followed by TRNSYS modelling and a retail electricity cost of \$0.30c per kWh.

How it Works

- 1. A fan draws in air, containing heat energy, across the evaporator
- 2. The evaporator turns the liquid refrigerant into a gas
- refrigerant into a hot gas
- 4. The hot gas inside the condenser coil heats the water inside the coil-wrapped tank
- 5. The refrigerant reverts back to a process to start again

¹ Energy use reduction based on CER (AS/NZS 4234) modelling, in Zone 3. ² Average COP is 4.15 based on AS/NZS 5125 test condition 2.



HP280



Smart Technology

With a Midea heat pump, set up and operation monitoring is made simple thanks to an amazing, in built user-friendly controller.

Operational modes

ECO (Heat Pump Only) mode: The standard mode where the highest efficiency is achieved

Hybrid Mode: The Heat Pump & E-heater operate together to ensure the set temperature is achieved

E-Heater: When the air temperature drops to below 5°C, the heat pump will automatically select E-heater mode for an electric hot water boost

EVAPORATOR



Low Operating Noise Operating at a very low 48/49 dBA you will hardly



Residential Warranty

5 Year Tank Cylinder (3 Year Labour) 3 Year Compressor (1 Year Labour)



Eligible for Government Incentives

170L Installed Unit

Midea hot water heat pumps qualifies to generate Small-scale Technology Certificates (STCs) under the Federal Government RET scheme and so Australian consumers can use these to reduce the point of sale price of their heat pump.





	<u> </u>	
Heat Pump Model	HP170	HP280
Nominal volume capacity (L)	170	280
Voltage / Hz / Phase	220-240 / 50 / 1	220-240 / 50 / 1
Element input power (W)	2150	3000
Heating capacity - Heat Pump Only (W)	1500	2000
Max water temperature (°C)	65	60
Max rated input power (W) / current (A)	2780 / 12.1	4000 / 17.3
Relief valve pressure (kPa)	1000	1000
Noise level (dBA)	48	49
Net Weight (kg)	90	154
Pipe connection diameter (mm)	DN20	DN20
Cylinder Type	Vitreous Enamel	Vitreous Enamel
Outdoor resistance class	IP24	IP24
Operating Mode Function	Manual	Manual
Refrigerant type/quantity	R134a / 0.8kg	R134a / 1.6kg





(6

Why choose Chromagen?

- o A leading provider of solar energy solutions with over 50 years history
- Offices Australia wide with a national dealer & service network
- A wide range of energy efficient solutions to suit your lifestyle
- o Committed to quality, innovation & energy-efficient solutions



chromagen.com.au | 1300 367 565

Efficient Water Heaters

Kitchen Appliances | Air Conditioning |

Solar Power Systems

This revision supersedes all previous versions. All details are accurate at time of publishing. Images indicative only - actual product configuration may differ. Product specifications may change without notice. For the latest product details and specifications, please visit our website - www.chromagen.com.au



Product Care

&

Maintenance Guide

75 - 89 Link Drive, Campbelffield Vic 3061

P: +61 3 9981 2500 F: +61 3 9981 2532

www.k-tcheninnovations.com.au

1 Page

CLEANING

Soiled surfaces or light stains may be removed with warm spapy water or with a common household detergent, non abrasive or any strong acidic or alkaline ingredients.

It may be necessary to cautiously use a brush similar to a tooth or nail brush. Wax or other polishes must not be used on decorative surfaces.

STAINS

Spills of any nature should be wiped up as soon as they occur. Laminates are resistant to most household products, however not absolutely stain proof? If a stain persists, it is suggested you apply a mild abrasive such as white toothpaste, with a soft toothbrush or cloth.

Never use a harsh abrasive or steel wool.

COMMON ADHESIVES AND PAINTS

May be removed cautiously with the following materials:

- 1. Alcohols (Methylated Spirits, Methanol)
- 2. Aromatics (Xylene, Petrol)
- 3. Aliphatics (Mineral Turpentine, Kerosene)
- 4. Oils (Mineral Oil, Vegetable Oil)
- 5. Ketones (Acetones, Nail Polish Remover)
- Ether Alcohols (Cello solves, Carbitoles)
- 7. Paint Thinners (Being a mixture of above)
- 8. Lacquer Thinners (Without the addition of Acid)

Note: Acidic based paint strippers must not be used

DANGER

Some of the above listed solvents are extremely flammable and vapours harmful. Keep away from heat, sparks and open flame. Keep containers closed. Avoid prolonged breathing of vapours. Avoid prolonged or repeated contact with skin.

Ensure there is adequate ventilation.

LAMINATE SURFACES, DOORS - PANELS - BENCH TOPS

Laminates are not scratch-proof but rather, scratch resistant.

It is possible to permanently scratch or mark the laminate surface with an uneven or sharpimplement.

Moisture will affect the board if allowed to penetrate the bench top joins (known as "Masons Mitre Joints").

Avoid a moisture build-up in these areas; wipe away spills as they occur.

Avoid using anything that may boil over (eg: Electric kettle, etc) on these Bench Top Joins.

SCORCH MARKS – BURNS

The use of a protective mat is highly recommended to prevent the surface being scorched when a hot pot or utensil is placed on the Bench Top.

The same applies to pans removed from hot plates or dishes taken from the oven, as their temperature in most instances would be in excess of 155°C (310°F).

The use of a wooden cutting board, or a commercially available heat resistant product is suggested.

DOORS – PANELS

These could be Vinvi (Membrane) Pressed Panels-Doors, Bar Back Panels, Lacquered Surfaces (Polyurethane) or Timber/Veneer Finishes.

Abrasive creams, powders and pastes may permanently alter the appearance of a laminate surface with continual use. Heavy rubbing will also denigrate the appearance.

Lacquered Surfaces (Polyurethane) or Timber/Veneer Finishes.

Never use products with a petroleum base, abrasive creams, pastes, or silicon/solvent based products on these surfaces.

Never allow hot or warm objects to come into contact with these surface finishes.

To maintain surface appearance use a warm moist cloth followed by a soft dry cloth whenever spills occur.

The application of furniture pollsh (in particular, ones which contain silicon) and waxes is not recommended on timber surfaces.

ADJUSTABLE SHELVES – ACCESSORIES

Heavy objects must be placed on the base of cabinetry, especially in the wider units, as this will make the shelves bow. Or "Heavy objects" could be placed to the side of fixed or adjustable shelves.

Never immerse any shelves or doors directly into water as this could cause the timber to warp or swell.

Decorated Board products should not remain in contact with hypochlorite bleach, caustic solution, hydrogen peroxide solution in any concentrations, mineral acid, sodium bisulphate, potassium permanganate in any concentration, berry juices, silver nitrate [1%] concentration), gentian violet in any concentration, mild silver protein, laundry blue dye or ipdine solution (alcohol contains 1% ipdine).

Sliding of heavy metallic or earthenware objects can cause scuffing of the surface. Fine scratches or scuff marks can often be removed by the application of a good quality can polish.

WARRANTY

Our warranty period for workmanship is 12 months, from the date of installation. If a site inspection is required outside that period a \$250 call out fee will apply. if the issue is deemed to be faulty workmanship, the fee will be refunded.

The following is not covered:

- reasonable wear and tear, or not maintained as recommended.
- covered by their own Warranty
- considered to be a manufacturing defect.

DISCLAIMER

The Company accepts no responsibility for any errors in this Guide. All suggested care and maintenance details are conveyed with the best intentions and the knowledge at the time of issue. Top Cat Installations Pty Ltd. Trading as Kitchen Innovations reserves the right to add, delete or change the product specifications or finishes, according the related contractual arrangements with the established pullders.

For more details refer to the Kitchen Innovations Web Site. www.kitcheninnovations.com.au

Other Services offered:

- Entertainment Units or Wall Units
- Alfresco Cabinetry
- o Wardrobes
- Stone/Granite Benchtops
- Metaline Splash Backs

1. Any damage caused by misuse, accidents, over exposure to heat or water,

Any other product/materials included in the kitchen, which are not manufactured by: Kitchen Innovations, such as, Appliances or other articles, are considered to be

3. Variations to, patterns, colours and textures of faminate, vinyi, solid timber natural characteristic's or polyurethane finishes, beyond Kitchen Innovations control, are not

Use & Care

Silestone & ECO Line Colour Series

- (ES) Uso y Mantenimiento
- (EN) Use & Care
- 🖭 Uso e Manutenção
- (DE) Gebrauch und Pflege
- (IT) Uso e Manutenzione
- 💷 Användning och Underhåll
- (FR) Utilisation et Entretien
- 🔊 Gebruik en Onderhoud





On Top

General Usage Advice

Routine Cleaning and Maintenance

Due to their low porosity, Silestone[®] and ECO Line Colour Series surfaces are highly resistant to household stains. Cosentino recommends you use Q-Action* to clean its Silestone[®] and ECO Line Colour Series surfaces. If you don't have this product, the best option is to use water and neutral soap. You should then finish off by rinsing the surface with plenty of water and drying it with kitchen paper or a clean cotton dishtowel.



* Note: For UK Market both CIF Acti Fizz and CIF Kitchen Spray may also be used.

Cleaning Stubborn Stains

When faced with stubborn stains, the best way to fix it depends on the type of stain. The most usual cases are:

Grease Stains

Apply Q-Action or similar (dishwasher soapy product) onto the stain and rub it with a sponge until it disappears. Repeat the process if necessary. Next, rinse with a generous amount of water and dry the affected area.

Limescale

Use cleaning vinegar and a damp sponge. If the stain persists, you can use a limescale remover that has been diluted with water. Never leave it on for more than 2 minutes. Repeat the process if necessary. Rinse with plenty of water and dry with paper.

Silicone and Putty Stains

We recommend you remove the stains as soon as they appear. To do so, use a knife held horizontally and CleanColorsil, and scrub with a sponge. If you don't have any CleanColorsil, you can use a wellknown brand of silicone remover. Afterwards, rinse with plenty of water and dry.

Cleaning Difficult Stains

For difficult stains, pour some Q-Action (or a similar product) onto the affected area and leave for 2 minutes. Next, scrub with a gentle scouring pad (for glass-top cookers, blue type: no scratch), rinse with plenty of water and dry. If the stain persists, contact the fabricator or studio who supplied you with your Silestone materials.

OTHER STAINS					
STAIN	PRODUCT	TOOL			
Food	Neutral Soap + Water	Wet Dish Cloth			
Ink	Alcohol Etilic*	Roll Paper			
Greasy Stains (Oil)	Neutral Soap + Water	Wet Sponge			
Oxid/Metal	Hydrochloric Acid*	Roll Paper			
Limescale	Antical Product/ Vinegar	Wet Sponge			
Other Stains (Coloring, Wine)	Diluted Bleach	Wet Sponge			

* Do not apply directly on the stain. To get wet the roll paper.

Response to Impacts

One of the most notable features of these surfaces is high impact resistance. However, you should avoid impact to those areas that are less resistant and more sensitive to impact along edges.

Avoiding Heat Damage

After using certain kitchen utensils, such as frying pans, pots and other items that give off heat, do not place them directly onto the surface. Instead, you should use a tablemat (a rubber one, if possible) until the utensils have cooled down. This is because the sharp difference in temperature (between hot and cold) can damage the surface.





🎒 Suede



Precautions for General Use

- Do not leave water on the surface for long periods of time. The most susceptible areas are those that are close to sinks.
- Do not use sharp objects to cut directly on the worktop surface. Instead, use other protective materials such as chopping boards.
- Do not place the surface outside or anywhere that may be exposed to high levels of ultraviolet radiation.
- Do not place any objects that give off heat, or that have been recently removed from the cooker, onto the surface. Use a trivet or tablemat.
- Do not use water-repellents, sealants, polishes or similar products.
- Do not polish the surface.
- Do not place heavy objects that are unsuitable for worktop use on the surface.
- Do not use paint strippers, caustic soda or any products with a pH greater than 10. If you use bleach or solvents, you should rinse the surface with plenty of water. Never leave such products in permanent contact with the surface, as they

Cleaning silicone and glue

During the fabrication (miter cutting, laminating, general cleaning of pieces) and the counter top installation (joints, splash backs, etc.) where glues, adhesives and silicones are used, we recommend to clean afterwards (maximum 30 minutes after gluing). To do so, use clean cotton cloths or paper. Use Clean Colorsil (Cosentino's complementary product) as a silicone and adhesive cleaner; Isopropyl Alcohol or Isopropanol (cleaning alcohol) or ethanol may be used instead.

Not recommended products

Products such as solvent or acetone should not be used for cleaning worktops or slabs. Scouring pads should not be used. It is advisable to use microfibre cloth or wet paper.

may affect it after 12 hours. Avoid the use of any chlorine-based products and any contact with hydrofluoric acid.

- Do not use grease removers with a high mineral content, or very strong products containing 50% solutions of hydrochloric acid or sodium hydroxide.
- Do not use any cleaning products that have a mineral content or that include microparticles in their composition.
- Do not use any scouring pads that may scratch the surface. Use a cleaning sponge.
- Examples of products that you must not use on Silestone and ECO Line Colour Series surfaces: paint strippers, oven-cleaning products, cleaning products containing methylene chloride, acids for unblocking plugholes or nail-polish removers containing acetone.
- If any of these products are spilled onto the surface, remove them as quickly as possible using plenty of water and neutral soap.
- The use of these types of products may result in the loss of the product warranty.

A product designed by **COSENTINO**[•]

COSENTINO HEADQUARTERS

Ctra. Baza a Huércal - Overa, km 59 , CP 04850 - Cantoria - Almería (Spain) Tel. +34 950 444 175, info@cosentino.com, www.cosentino.com, www.silestone.com silestonetheoriginal @@silestone_ESP



* To check terms and conditions please go to www.silestone.com ** To obtain more information about colours with NSF certificate please visit the official website: www.nsf.org



WARRANTY









www.windowsanddoors.build

The Southern Star Group comprises SOUTHERN STAR WINDOWS (ACN 100012431) and AURORA AUSTRALIS HOLDINGS PTY LTD (ACN 130 653 575) trading as CANTERBURY WINDOWS AND DOORS and HOMEVIEW WINDOWS AND DOORS (the "Southern Star Group"). Each member of the Southern Star Group is a member of the Australian Window Association and, as such, conforms to an industry Code of Conduct designed to protect consumers. Products manufactured by members of the Southern Star Group are inspected by Independent, third party NATA accredited auditors to validate that the window and door products examined have been manufactured to the relevant Australian Standards and the legislative requirements of the National Construction Code of Australia. Subject to the conditions and limitations listed under "General Conditions" below, each member of the Southern Star Group: (a) guarantees that its products are of acceptable guality and free of any defect caused by the manufacturer; and (b) warrants its products against defects arising from faulty workmanship or materials and, in the case of timber windows and doors, insect attack and decay, for a period of seven (7) years from the date of delivery by the member of Southern Star Group. (the "Warranty").

General Conditions

- The Warranty is subject to the following conditions and limitations:
- recommendations.
- · The product has not been subject to misuse, abuse or neglect.
- · Damage has not been caused by accident, transport, installation or any external cause.
- · In respect of insect and safety screen products, the Warranty is void and will not apply if: a. The product has not been fabricated by a member of Southern Star Group. b. The product has not been fitted by Southern Star Group personnel or nominated installers.
- componentry.
- such as Low 'E' coated glass prducts.
- acclimatisastion has occurred at final altitude.
- year only.
- beyond the original delivery date at the request of the customer.
- other door parts are covered for a period of one (1) year only.
- assigned to the person to whom the goods are supplied.
- · For Timber products in particular:
- no further than 500mm apart.
- -Within thirty (30) days of delivery a first coat of paint, varnish or sealer must be applied to all surfaces. LRV approx 5.
- The Warranty will be void when a dark coloured stain or paint has been applied to external timber surfaces. consistency, or grain configuration.
- fallen below 12% or risen above 18% is not deemed a defect. · For Doors in particular:
- for lights, louvres, panels or any other special features. 1500mm or higher than 2330mm; or doors that are improperly hung or which do not swing freely.

The Warranty is provided in addition to any warranty or guarantee imposed by law which cannot be excluded and, in particular, the guarantees implied by the Competition and Consumer Act 2010. In no way does this guarantee seek to exclude or limit any right or remedy you have in law which cannot be excluded. However, to the extent that is permitted by law, any other warranties or guarantees are excluded.

The product has been installed in accordance with the relevant Australian Standards and best building practice.

The product has been installed and maintained in accordance with Southern Star Group installation and care and maintenance

The Warranty is void if the purchaser has provided incorrect measurements or specifications.

· Manufacturing standards and tolerances are not deemed defects, nor are industry variations in colour of aluminium and timber

The Southern Star Group accepts no liability for thermal cracking of glass, which is not uncommon in thermally efficient glasses.

 This warranty does not apply to insulated glass units installed at altitudes of 800 meters or more above mean sea level, unless breather tubes or capillary tubes have been installed and these tubes have subsequently been sealed after sufficient

Wire reinforced glass, toughened glass, float glass, laminated glass and mirror glass have the benefit of the Warranty for one (1)

Southern Star Group accepts no responsibility for glass breakage (except for faulty workmanship or material).

· Southern Star Group accepts no responsibility if damage occurs to product when it is kept in storage by Southern Star Group

Moving parts such as winders, hinges, jambliner system, counter balance system, sash locks, handles and other moving parts/all

 The Warranty does not apply to parts supplied by other manufacturers as separate components, and where such a component is warranted or guaranteed by its manufacturer or supplier, those guarantees or warranties, whether express or implied, are

 The Warranty is limited to the repair or replacement of the faulty product at the Southern Star Group's discretion but does not extend to the installation or refurnishing of a replacement product or any other consequential or indirect loss or damage incurred as a result of the defect. No claims can be made against any member of the Southern Star Group in respect of such matters.

Only repairs carried out by Southern Star Group personnel or authorised Southern Star Group agents are covered by the Warranty.

-When delivered, doors must be stored in a dry area and not in damp, moist or freshly plastered areas; and stored flat on bearers

-Light coloured finishes must be applied to external timber surfaces in the manner and frequency specified by the Company or paint manufacturer for the term of the Warranty to reduce the possibility of bow, twist or warp. Light reflective semi gloss finishes are recommended. Paint with a light reflectance value (LRV) finish greater than 50 should be used : White - LRV approx, 95 Black-

-The Warranty does not cover any circumstances arising in regard to any natural variations of timber product, shade, surface

-Warp (cupping, bowing, twisting or distorting of timber) less than 5mm; or exceeding 5mm where moisture content of timber has

-When fitting doors, the structural strength must not be impaired when fitting or applying hardware or cutting or altering the door

-All solid doors must be hinged with 3 appropriately sized hinges and not more than 3mm may be trimmed from any edge. -The Warranty does not cover glass doors that are wider than 1020mm or higher than 2635mm, sliding door panels wider than

Care & Maintenance

Warranty Claims

Claims under the Warranty require the claimant to first notify the manufacturer. No claim by the customer, whether for alleged damage or defective goods or any other cause whatsoever, need be recognized by the Southern Star Group (and all such claims shall be deemed absolutely waived by the customer) unless notified in writing and received within one month (30 days) of the defect arising or being identified in the product.

Claims under the Warrantly can only be made by the purchaser of the product. Copies of documentation showing the purchase date of the product should be included with the written claim and forwarded to the branch from which the product was purchased. Branch contact details appear on the back page of this document, Any costs associated with lodging a claim under the Warranty will be borne by the claimant.

Where a product has been repaired or replaced, the Warranty shall apply to the repaired or replaced product for the balance of the period provided by the Warranty.

Care and Maintenance Recommendations

To keep your windows and doors looking and functioning at their best, we recommend you maintain them regularly. To maintain optimum aesthetic and performance, follow these simple maintenance and care tips.

All Aluminium Windows and Doors

External aluminium surfaces of windows and doors should be washed with clean water and a mild detergent at least every three months. A soft sponge or similar should be used to avoid scratching the glass or aluminium. In coastal or industrial areas where the environmental conditions are more demanding, the cleaning program should be carried out on a monthly basis. Abrasive, chemical cleaners or steel wool should not be used as such methods may result in damage to the glass or aluminium surfaces. Drainage slots should be checked on a regular basis to ensure they have not become blocked with residual dirt or grime.

Timber Windows and Doors

Use soft, clean cloths and do not use scraping devices or abrasive cleaners. Wash down with a soft cloth and mild detergent. Rinse off residue with clean water, Do not use solvents. Keep bottom tracks clean, wipe with a cloth and use a dry silica based lubricant if required, lightly grease top tracks, oil hinges. Opening sashes should be operated on a regular basis to ensure the sash hardware continues to move smoothly.

Awning/Casement Windows and French Doors

With sashes open, the sash and opening perimeter should be cleaned regularly and kept clear of dust and foreign matter. All door and window operating hardware should be cleaned and operated regularly to ensure smooth operation. Lubricants should not be used on casement stays, as this will affect their operation.

Sliding Windows and Sliding Doors

Sill recesses should be regularly cleaned and kept clear of dust and foreign matter. A brush and vacuum within the track area may be used to do this. Door locks should be checked from time to time for satisfactory operation and may require adjustment to compensate for building settlement. Door rollers are factory set and should not require any adjustment. However, if, due to building settlement, an adjustment needs to be made, the door panel must first be lifted to relieve weight from the roller assembly. Adjustment should be made using a Phillips head screwdriver.

Double Hung Windows

Window jamb tracks should be cleaned regularly and kept clear of dust and foreign matter. Window operating hardware should be cleaned and operated regularly to ensure smooth operation.

Hardware

Regular maintenance is required for all hardware, even stainless steel, as they are moving parts. In most environments, maintenance is recommended every six (6) months and every three (3) months in marine and industrial environments. Hangers, pivots and brackets should be given a light spray of corrosion preventative (such as CRC Marine 66, Inn ox orWD40) followed by a light wipe with a dry cloth to remove excess. Exposed surfaces should be wiped down with warm soapy water and a soft rag and then rinsed clean before applying preventative. Visible surfaces of hinges should be wiped down with warm soapy water on a soft rag and then rinsed off by wiping with a clean damp rag. Application of a thin film of light machine oil or one of the corrosion preventative sprays mentioned above will help to maintain the original lustre of the metal finish. Be careful not to get these compounds on the timberwork itself as they may cause staining. Drop bolts should be sprayed with a lubricant such as those mentioned above and the sliding pin inside the bolt and to the lock cylinder.

Glass

It is recommended that all glass surfaces be kept clean by prompt removal of all dirt or other contaminants. Clean water and, in some instances, a small amount of mild detergent should be used. After washing, any detergent residue must be thoroughly rinsed away with clean water. Under no circumstances is any form of blade, scraper or abrasive cleaner to be used. Stubborn dirt or residue should be lightly sponged off to avoid scratching of the glass. The frequency of cleaning required will depend on environmental conditions such as proximity to the ocean or industrial areas. As a general guide, glass should be cleaned at least quarterly.

Insect and Safety Screens

Flyscreens can be cleaned by vacuuming or washing thoroughly using a soft brush. Screens should be cleaned at least three to four times per year. A small amount of detergent can be added to a bucket of warm water. Carefully remove the screen before hosing it down thoroughly. A soft nylon brush can be used to dip into the warm water and detergent, gently brushing the screen. Ensure to hose down well afterwards and allow the screen to dry before replacing in the window or door.



SOUTHERN STAR GROUP HEAD OFFICE + SHOWROOM

NORTH GEELONG 5 Kelly Court PO Box 563 North Geelong Vic 3215 P 03 5277 7200 F 03 5277 7222

SOUTHERN STAR ALUMINIUM WINDOWS + DOORS OFFICES + SHOWROOMS

MELBOURNE | 261 Princess Highway Hallam Vic 3803 | P 03 8786 3555 | F 03 8786 3444

SYDNEY 40 Lyn Parade Prestons NSW 2170 P 02 9426 7400 F 02 9426 7444

BRISBANE GOLD COAST | 55 Motorway Circuit Ormeau QLD 4208 | P 07 5549 5600 | F 07 5549 5611

PORT MACQUARIE | 39 Uralia Road Port Macquarie 2444 | P 02 6581 0908 | F 02 6581 2190

HUNTER | 1 Mayfair Close Morisset NSW 2264 | P 02 4980 1100

CANTERBURY TIMBER WINDOWS + DOORS OFFICES + SHOWROOMS

MELBOURNE | 590 Heatherton Road Clayton South Vic 3169 | P 03 9549 7333 | F 03 9549 7362 | E info@windowsanddoors.build



FOR YOUR NEAREST BRANCH CALL OUR TOLL FREE NUMBER 1300 733 599





www.windowsanddoors.build

SOUTHERN STAR **Group of Companies**

- ADELAIDE | 19 Tappa Road Edinburgh Park SA 5111 | P 08 8256 9500 | F 08 8256 9555







If you have any further queries, please contact a member of the Habitas team on the below. e <u>Habitas@development.vic.gov.au</u>



A project by





